

## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 08/04/2022

User ID : CatherineLee

### Section A - Accident Details

Registration Number	SMB319S
Case Reference Number	BUS/03/22/7001
Registration Date	16/10/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Seng Han Feng
Type of Accident	Side Swipe
Accident Date and Time	4/3/2022 6:19 AM
Accident Reported Date and Time	4/3/2022 7:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114234
Special Instruction to ARC, if any	SMB319S - Front right windscreen cracked and headlight cover cracked PA9929S (TP) - INSURED WITH NTUC
Prepared Date and Time	8/3/2022 2:25 PM
Chassis Number	WMAA22ZZ0C7001451
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$616.00	\$446.00
Total Spare Part Cost	\$6,582.44	\$5,931.27
Total Other Cost	\$0.00	(\$407.20)
<b>TOTAL COST</b>	<b>\$9,318.44</b>	<b>\$7,560.07</b>
<b>Lump Sum Total</b>	<b>\$9,300.00</b>	<b>\$7,550.00</b>
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kok Khoon Goh	Rasul
ARC / Surveyor Sign Off Date	08/03/2022 2:31 PM	08/03/2022 5:10 PM
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/04/2022

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	\$1,590.00
<b>Total Labour</b>	<b>\$2,120.00</b>	<b>\$1,590.00</b>

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	\$446.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$616.00</b>	<b>\$446.00</b>

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$0.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$407.20)
<b>Total Other Costs</b>	<b>\$0.00</b>	<b>(\$407.20)</b>

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010148	GLASS	4001X01-GLASS5171	WINDSCREEN,FRONT:F OR MAN A22 BUS	1.00	\$5,031.80	10.00	\$4,528.62	Replace	Replace
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
6000917			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	Replace
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010305	VE	81.25101-6540	HEADLAMP,RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
6010307	VE	81.25320-6112	FLASHER,AUX HEADLAMP,RH (MAN BUS)	0.00	\$904.40	0.00	\$0.00	Replace	Not Given
<b>Total</b>					<b>\$8,746.50</b>		<b>\$7,414.09</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									