

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002198/KEA3Q2**Date:** 19/07/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100397778
Claimant Vehicle No :	SMR6472H	Insured Vehicle No :	SDN312D
Date of Loss:	06/03/2022	Nature of Claim:	TP
		Claim No:	6652378740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR6472H		
Make & Model:	TOYOTA VOXY HYBRID, 1.8 V CVT (A)	Engine No:	2ZR0E36430
Reg. Date:	16/01/2020 (Man. Year: 2019)	Chassis No:	ZWR800405259
Colour:	Metallic Silver	Odometer:	96622 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,969.80	2,369.66	4,600.14	66.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,325.00	1,525.00	53.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,819.80	3,694.66	6,125.14	62.38
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	9,819.80	2,950.00	6,869.80	69.96
+ GST 7.00/7.00% (S\$)	687.39	206.50	480.89	69.96
Nett Amount (S\$)	10,507.19	3,156.50	7,350.69	69.96
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
Nett Liability (S\$)		3,636.50		

INSPECTION

Date of Assignment:	08/03/2022	Yee Auto Pte Ltd (HQ)
Date Inspected:	08/03/2022 Inspected At:	160 SIN MING DRIVE #02-17 SIN MING AUTOCITY
Estimated Period of Repair:	4.0 days	Singapore 575722

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,648.20 F	*798.20 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*REAR BUMPER REFLECTOR -LH	Serviceable	125.00 F	*- FL
4	1		*REAR BUMPER REFLECTOR -RH	Serviceable	125.00 F	*- FL
5	1		*REAR BUMPER SIDE RETAINER -LH	Serviceable	68.40 F	*- FL
6	1		*REAR BUMPER SIDE RETAINER -RH	Serviceable	68.40 F	*- FL
7	1		*REAR END PANEL	Repair	668.20 F	*- FL
8	1		*REAR TAILGATE	Bent	2,480.30 F	*1,645.25 FL
9	1		*REAR TAILGATE EMBLEM -HYBRID	Necessary	88.00 F	*88.00 FL
10	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	825.10 F	*- FL
11	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 F	*- FL
12	1		*REAR TAILGATE LOCK	Repair	285.10 F	*- FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	178.10 F	*178.10 FL
14	1		*SET REVERSE SENSOR	Cracked	300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,969.80	3,059.55
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	689.89
Total Parts (\$\$)	6,969.80	2,369.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,200.00	500.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,000.00	600.00
3	TO APPLY RUST-PROOFING ON REPAIRED REPLACED PANEL	New	180.00	30.00
4	TO REMOVE/REFIX REAR WINDSCREEN TO FACILITATE REPAIRS	New	200.00	120.00
5	TO REMOVE/TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
6	TO CHECK WIRING FUNCTIONS & WATER LEAKAGE	New	120.00	15.00
Gross Labour Cost (\$\$)			2,850.00	1,325.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >