

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: ALANO Ana Maria Velarde

Date: 14 Mar 2022

Preliminary Advice

Vehicle No	: SMS4916C	Accident Date	: 05/03/2022
Make	: MINI COOPER	Policy No.	: MP314086
Assignment Date	: 09/03/2022	Excess	: S\$0.00
Date of Inspection	: 09/03/2022	Est. Duration of Repair	: 5
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD (HQ) 38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB SINGAPORE 608581		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 8,215.20	(Estimate \$7,327.95 + Supplementary \$887.25)
Revised Amount	:S\$ 7,108.45	
Check Items (Estimated)	:S\$ 68.25	
Total	:S\$ 7,176.70	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 95,000.00

COE / PARF Rebate	:S\$ 43,931.00
Salvage Value	:S\$
Margin for Repair	:S\$ 51,069.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.