



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0179/2022/GW
DATE : 9-Mar-22
WIP :

VEHICLE IN WORKSHOP. KINDLY ARRANGE SURVEY 11/3/22
YOUR INSURED VEH NO : SKA 4680 A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR YIN KAH KIT
ADDRESS : BLK 285D TOH GUAN ROAD
#15-62
SINGAPORE 604285
TELEPHONE : HP +65 92966086
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SP2000729837-01
VEHICLE NO : **SKE 6700 S**
MODEL CODE : AUDI Q7 3.0 TFSI QU
MODEL YEAR : 11/1/2012
ENGINE NO : CJT047697
CHASSIS NO : WAUZZZ4L8CD017919
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Mar-22
PLACE OF ACCIDENT : 109 BUKIT BATOK WEST AVE 6
SINGAPORE 650109



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 6700 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 900.00 500	
3	TO REMOVE AND RENEW AIR CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 2,000.00	✓
4	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 450.00 280	
5	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES.	S/N \$ 2,800.00	✓
6	TO RENEW ALTERNATOR, THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$ 980.00	?
SUB TOTAL LABOUR CHARGES		: \$ <u>7,610.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 6700 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILLITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$ 2,400.00	✓
8	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00	✓
9	TO PLACE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	✓
10	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT AND BOTH FRONT CHASSIS FRAME COVER PLATES AND BOTH FRONT CHASSIS FRAME. TO ALIGN BACK BOTH CHASSIS MEMBERS INTO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 19,000.00	8400
11	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT FENDER TOP SUPPORT, BOTH FRONT CHASSIS FRAME WITH COVERS, BOTH UPPER A-PILLARS, BOTH FRONT DOOR AND DOOR COVER.	\$ 11,000.00	5000 6 x 600 = 3600 Hing x 2 = 200 Fender Top Support = 300 Chassis Frame x 2 = 500 Door Cover x 2 = 400 <u>5000</u>
12	TO CARRY OUT ALUMINUIM PRIMER WORKS.	S/N \$ 980.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 36,580.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 6700 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
14	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	✓
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 45,374.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 3,767.00	✓
2	FRONT BUMPER FIXING PARTS <i>in</i>	1	\$ 259.00	✓
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>crack</i>	1	\$ 265.00	✓
4	NOISE INSULATION <i>Missing</i>	1	\$ 512.00	✓
5	FRONT BUMPER COVER - LH / RH <i>LH Missing</i>	2	\$ 156.00 78	
6	FRONT BUMPER SPOILER - LH / RH <i>LH Missing</i>	2	\$ 126.00 63	
7	RADIATOR GRILLE <i>crack</i>	1	\$ 1,804.00	✓
8	FOAM FILLER PIECE <i>crack</i>	1	\$ 192.00	✓
9	FRONT REINFORCMENT BEAM <i>Bent</i>	1	\$ 927.00	✓
10	FRONT BUMPER HOLDER - LH / RH	2	\$ 846.00	✓
11	FRONT BUMPER SUPPORT - LH / RH <i>Distorted</i>	2	\$ 106.00	✓
12	FRONT BUMPER GUIDE PIECE - LH / RH	2	\$ 158.00	✓
13	FRONT BUMPER COVER - UPPER <i>Missing</i>	1	\$ 167.00	✓
14	STICKER FOR AIR CONDITIONER <i>in</i>	1	\$ 34.00	✓
15	FRONT SENSOR - LH / RH <i>LH end</i>	2	TBC	1/2
16	FRONT SENSOR - LH / RH CENTRE <i>LH end</i>	2	TBC	1/2
17	FRONT BUMPER WIRING <i>?</i>	1	\$ 750.00	?
18	HORN BRACKET <i>Bent</i>	1	\$ 54.00	✓
19	FRONT HORN - LOW TONE <i>in</i>	1	\$ 154.00	+
20	FRONT HORN - HIGH TONE <i>in</i>	1	\$ 240.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,517.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER - LH / RH <i>LH Distorted, RH Panel let</i>	2	\$ 4,326.00	✓
22	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 67.00	✓
23	FRONT FENDER SEAL - LH / RH <i>LH Distorted</i>	2	40.00 20	
24	FRONT FENDER BRACE - LH / RH <i>LH Distorted</i>	2	164.00 84.	
25	FRONT FENDER CLOSING ELEMENT - LH / RH UPPER <i>LH Rnd</i>	2	44.00 22	
26	FRONT FENDER CLOSING ELEMENT - LH / RH <i>3 LH Rnd</i>	2	286.00 143	
27	FRONT FENDER SECURING BRACKET - LH / RH	2	34.00 17.	
28	FRONT WHEEL HOUSING LINER - LH / RH <i>LH form</i>	2	598.00 299.	
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>LH Rnd</i>	1	114.00 57.	
30	INSCRIPTION 'S - LINE' <i>new</i>	2	\$ 266.00	✓
31	BONNET <i>Distorted</i>	1	\$ 7,363.00	✓
32	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 93.00	+
33	BONNET LID HINGE - LH / RH <i>RH Bent</i>	2	\$ 382.00	—
34	BONNET HINGE COVER - LH / RH <i>new</i>	2	\$ 104.00	+
35	BONNET GAS FILLED STRUR <i>new</i>	1	\$ 154.00	+
36	BONNET CATCH HOOK <i>new</i>	1	\$ 110.00	+
37	BONNET LID LOCK <i>new</i>	1	\$ 228.00	+
38	BONNET LID LOCK BRACKET <i>new</i>	1	\$ 63.00	+
39	BONNET LID LOCK CABLE <i>3 new</i>	1	\$ 109.00	+
40	BONNET LID LOCK GRIP	1	\$ 71.00	+
SUB TOTAL SPARE PARTS			\$ 14,616.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL - 6366 2323 FAX - 6841 1183
 EMAIL - NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	BONNET LID LOCK CABLE <i>new</i>	1	\$	82.00	✓
42	BONNET LID LOCK ABLE COVER <i>new</i>	1	\$	94.00	✓
43	BONNET SEAL - LH / RH <i>3 per</i>	2	\$	46.00	✓
44	BONNET SEAL - FRONT	1	\$	119.00	✓
45	BONNET SEAL - UPPER FRONT <i>new</i>	2	\$	89.00	✓
46	HEADLIGHT MOUNTING - LH / RH <i>could</i>	2	\$	446.00	✓
47	HEADLIGHT - LH / RH <i>could</i>	2	\$	7,816.00	✓
48	HEADLIGHT CONTROL UNIT - LH / RH <i>not in</i>	2	\$	2,474.00	+
49	HEADLIGHT GAS DISCHARGE - LH / RH <i>LH only</i>	2	\$	906.00 453.	
50	VENT HOSE - LH <i>distorted</i>	1	\$	97.00	✓
51	VENT HOSE - RH <i>new</i>	1	\$	26.00	+
52	HEADLIGHT ASSEMBLY SPACER - LH / RH <i>distorted</i>	2	\$	91.00	✓
53	HEADLIGHT ADJUSTMENT ELEMENT <i>LH only</i>	6	\$	305.00 157.50	
54	HEADLIGHT SPACER - LH / RH <i>LH only</i>	2	\$	97.00	48.50
55	HALOGEN FOG LAMP - LH / RH <i>LH missing</i>	2	\$	896.00 498	
56	LED TURN SIGNAL - LH / RH <i>LH missing</i>	2	\$	2,362.00 1181	
57	HEADLIGHT NOZZLE CARRIER - LH / RH <i>LH scratched</i>	2	\$	456.00 278.	
58	HOSE FOR HEADLIGHT WASHER SYSTEM <i>?</i>	5	\$	215.00	?
59	PUMP FOR HEADLIGHT WASHER SYSTEM <i>missing</i>	1	\$	171.00	✓
60	FLAT CONTACT HOUSING <i>only</i>	1	\$	45.00	✓
SUB TOTAL SPARE PARTS			:	\$ 16,833.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	PUMP FOR WINDSCREEN WASHER SYSTEM <i>new</i>	1	\$	137.00	+
62	WASHER WATER RESERVOIR <i>new</i>	1	\$	191.00	+
63	SPRAY NOZZLE FOR FRONT WINDSCREEN - LH / RH <i>new</i>	2	\$	230.00	+
64	FRONT LOCK CARRIER <i>could</i>	1	\$	1,437.00	✓
65	BONDED RUBBER MOUNTING BRACET <i>new</i>	2	\$	12.00	✓
66	FRONT CROSS MEMBER - LOWER ?	1	\$	333.00	?
67	A/C CONDENSER ?	1	\$	1,053.00	?
68	A/C CONDENDER SEAL ?	1	\$	53.00	?
69	A/C SUCTION HOSE <i>Best</i>	1	\$	730.00	✓
70	A/C HOSE <i>Best</i>	1	\$	541.00	✓
71	A/C DISCHARGE HOSE <i>Best</i>	1	\$	423.00	✓
72	A/C SUCTION LINE <i>Best</i>	1	\$	671.00	✓
73	RADIATOR <i>could</i>	1	\$	1,745.00	✓
74	RADIATOR GROMMET - UPPER <i>new</i>	2	\$	63.00	✓
75	RADIATOR PROFILE RUBBER - LOWER <i>new</i>	2	\$	143.00	✓
76	ADDITIONAL RADIATOR <i>Distorted</i>	2	\$	1,899.00	✓
77	RESERVOIR <i>new</i>	1	\$	1,091.00	+
78	RADIATOR COOLANT <i>new</i>	6	\$	228.00	✓
79	RADIATOR BRACKET ?	1	\$	17.00	✓
80	RADIATOR END CAP <i>new</i>	1	\$	38.00	✓
SUB TOTAL SPARE PARTS		:	\$	11,035.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	RADIATOR TWIN FAN RING ?	2	\$ 535.00	?
82	RADIATOR FAN - LH	1	\$ 1,380.00	+
83	RADIATOR FAN - RH <i>men</i>	1	\$ 1,509.00	+
84	RADIATOR AIR GUDIE - LH / RH <i>LH mgd</i>	2	\$ 64.00 32	
85	RADIATOR AIR GUIDE - UPPER <i>Missing</i>	1	\$ 48.00	✓
86	RADIATOR AIR GUIDE - LOWER <i>men</i>	1	\$ 36.00	+
87	RADIATOR AIR GUIDE - LH / RH FRONT <i>LH Distorted</i>	2	\$ 128.00 64	
88	RADIATOR SEAL - LH / RH ?	2	\$ 60.00	?
89	RADIATOR BEADING ?	2	\$ 94.00	?
90	AIR FILER <i>men</i>	1	\$ 704.00	+
91	INTAKE HOSE <i>men</i> ?	1	\$ 412.00	+
92	INTAKE MANIFOLD <i>men</i>	1	\$ 124.00	+
93	WATER DRAINAGE HOSE <i>men</i>	1	\$ 37.00	+
94	COMPRESSOR <i>wt</i>	1	\$ 8,629.00	✓
95	THROTTLE VALVE ADAPTER ?	1	\$ 1,581.00	?
96	THROTTLE VALVE CONTRIM ELEMENT ?	1	\$ 1,142.00	?
97	ENGINE SUPPORT - LH ?	1	\$ 178.00	?
98	ENGINE SUPPORT - RH <i>men</i>	1	\$ 113.00	+
99	ENGINE MOUNTING ?	1	\$ 429.00	?
100	ENGGINE BRACKET ?	1	\$ 2,116.00	?
SUB TOTAL SPARE PARTS			\$ 19,319.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	FRONT SHOCK ABSORBER MOUNTING - LH / RH <i>new</i>	2	\$ 238.00	X
102	FRONT FENDER SUPPORT - LH / RH <i>LH Distorted</i>	2	\$ 384.00 192	
103	FRONT SIDE MEMBER - LH / RH ?	2	\$ 2,284.00	?
104	FRONT SIDE MEMBER EXTENSION - LH ?	1	\$ 1,261.00	?
105	FRONT SIDE MEMBER EXTENSION BRACKET - LH ?	1	\$ 40.00	?
106	FRONT ALUMINIUM RIM - LH <i>new</i>	1	\$ 3,020.00	X
107	RUBBER VALVE <i>new</i>	4	\$ 15.00	X
108	FRONT CROSS MEMBER ?	1	\$ 4,503.00	?
109	FRONT WISHBONE - LH UPPER ?	1	\$ 840.00	?
110	FRONT WISHBONE - LH LOWER ?	1	\$ 84.00	?
111	FRONT WHEEL BEARING - LH ?	1	\$ 1,272.00	?
112	FRONT WHEEL BEARING BRACKET - LH ?	1	\$ 587.00	?
113	FRONT WHEEL HUB - LH ?	1	\$ 467.00	?
114	FRONT WHEEL BEARING WITH ASSEMBLY ?	1	\$ 510.00	?
115	HEADLIGHT LEVEL CONTROL WITH SENSOR - LH ?	1	\$ 851.00	?
116	FRONT GAS SHOCK ABSORBER - LH ?	1	\$ 921.00	?
117	FRONT ANTI ROLL BAR ?	1	\$ 783.00	?
118	FRONT COUPLING ROD ?	1	\$ 145.00	?
119	FRONT DRIVE SHAFT <i>new</i>	1	\$ 1,838.00	X
120	FRONT STEERING GEAR <i>new</i>	1	\$ 6,361.00	X
SUB - TOTAL SPARE PARTS		:	\$ 26,404.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	FRONT TRACK ROD - LH ?	1	\$ 353.00 ?	
122	SPLASH SHIELD ?	1	\$ 756.00 ?	
123	SPLASH SHIELD CENTER ?	1	\$ 781.00 ?	
124	FRONT DOOR - LH <i>Repld</i>	1	\$ 5,708.00 ✓	
125	FRONT DOOR OUTER SEAL - LH <i>nc</i>	1	\$ 463.00 ✓	
126	FRONT DOOR SPACER <i>nc</i>	2	\$ 5.00 X.	
127	FRONT DOOR ATTACHMENT PARTS - LH <i>nc</i>	1	\$ 102.00 +.	
128	FRONT DOOR FOAM - LH <i>nc</i>	2	\$ 63.00 +	
129	FRONT DOOR HINGE - LH <i>nc</i>	1	TBC +	
130	FRONT DOOR HINGE - LH LOWER <i>nc</i>	1	TBC +	
131	FRONT DOOR CIVER - LH <i>nc</i>	1	\$ 396.00 +	
132	FRONT SIDE MIRROR EXTERIOR MOUNTING - LH <i>nc</i>	1	\$ 1,752.00 +	
133	FRONT SIDE MIRROR CAP - LH	1	\$ 461.00 +	
134	FRONT SIDE MIRROR TURN SIGNAL - LH <i>nc</i>	1	\$ 181.00 X	
135	STATIC MIXER	1	\$ 12.00 ✓	
136	2 PACK EPOXY ADHESIVE	1	\$ 122.00 ✓	
137	ALUMINIUM POWDER	1	\$ 637.00 ✓	
138	HARDENER	1	\$ 232.00 ✓	
139	ALUMINIUM PRIMER	1	\$ 233.00 ✓	
140	CLEANING BLOCK	1	\$ 96.00 ✓	
SUB TOTAL SPARE PARTS			\$ 12,353.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 6700 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
141	STONE CHIP	S/N	\$ 180.00	✓
142	ACRYLIC SEALANT	S/N	\$ 180.00	✓
143	CAVITY WAX	S/N	\$ 140.00	✓
144	FRONT NO. PLATE	S/N	\$ 60.00	✓
145	SUNDRIES		\$ 1,000.00	?
TOTAL SPARE PARTS		:	\$ 112,637.00	
TOTAL LABOUR CHARGES		:	\$ 36,580.00	
GRAND TOTAL		:	\$ 149,217.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *10/03/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *1st Authorised, 22 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT