



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205052

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 16/08/2022
Reference CC3/CTI22002210/Kea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHF 721B
Insured Veh. PA 9645K
Claim No. SNM22D201635/C02
Policy No. DMB1SNW00005512100
Accident Date 08/03/2022
Inspection Date 08/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22002210/Kea3q2	
			Date: 16/08/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PA 9645K	Veh. Inspected	SHF 721B
	Policy No.	DMB1SNW00005512100	Coverage (\$)	0.00
	Claim No.	SNM22D201635/C02	Excess (\$)	0.00
	Assign From		Assign Date	08/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JTDKB3FU803092617	Colour	M.P.WHITE /RED
	Odometer	32805 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DUNLOP	5 mm
	L/H Front Tyre	195/65 R15	DUNLOP	5 mm
	R/H Rear Tyre	195/65 R15	DUNLOP	5 mm
	L/H Rear Tyre	195/65 R15	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S DOOR MIRROR. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/03/2022	Inspection Date	08/03/2022
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 721B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	BROKEN		
	MIRROR ASSY ,OUTER REAR VIEW ,LH		1,339.30	1,339.30
	LESS 25% DISCOUNT		-334.83	-334.82
			1,004.47	1,004.48
	<u>LABOUR</u>			
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,600.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
GRAND TOTAL			3,154.47	1,129.48
RECOMMENDED COST OF REPAIRS				1,129.48

Report Ref No. CC3/CTI22002210/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 721B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 721B

RE-INSPECTION

