

ASS. REQ. BY:

REF:

C74 220022101ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01

days

Res.: Yes or No

Lum Sum:

1-B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/H = 7213

Yr Regn:

11 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M. P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

32805

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J7DKB3FU 80.3092617

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

8/3/22

D.O.I.

8/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S down mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 CRIA not ready

9/3 @ 1129.48 Carhu

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fees:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Withheld
Resurvey B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF721B

81129.48

AAD2202-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF721B

JTDKB3FU803092617

200303878K

TOYOTA

PRIUS GEN 4

08/03/2022

PA9646K/Chia

30/11/2021

08 MAR 2022

PART

- 1 MIRROR ASSY, OUTER REAR VIEW, LH

LIST

\$	Bro	1,339.30
TOTAL	\$	1,339.30
25%	\$	334.83
\$		1,004.48

Special Nett

TOTAL

\$ -

TOTAL PARTS \$ 1,004.48

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00

To Check Electrical Lighting Concerned.

\$ 170.00

TOTAL \$ 2,150.00

Over All Total \$ 3,154.48

LKK Auto Consultants hence notify the Repairer of the following:
(PART-BY-PART) Repair Days

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

20 days
1 day