

Ref: Thuan

NS/INC22002215/Vtc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No **MT/1163057-002**

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sunt: _____ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

part by part \$4039.58, 3days
red:2201.92;35%

Veh No: **SH8884X**

Yr Rogn: **30/9/20**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai**

long

c.c. **1580**

Colour: **blue**

AC: Insured / Std / HI / NA

Sp Reading: **136486**

T/Radio: Insured / Std / HI / NA

Eng/No: _____

C/No: **hmtk851CULU189691**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inter** / Jammed / Leaked / Burnt or

Brake: **Inter** / Jammed / Leaked / Burnt or

Mod: **Nil** / S/Rim / STD A/Rim or

Tyre Size: **F: 195/65R15**

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal. **5** mm

R/Bal. **5** mm

L/Bal. **5** mm

L/Bal. **5** mm

D.O.A. **25/2/22**

D.O.I. **25/2/22 17/5**

Survey held at

CDGE

Des. of Damages: Frt / Rear / **O/S** / NIS / VIC / Roof/Top or

The VIC / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time File Return to?

Days Of Repair: **3**

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

☐

Visual and (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fuels

Others

Total

Request Form 24:

Date/Time File Return to?

Date/Time: 25.02.2022 14:46

Page : 1

Item: ARC Repair TP(CLSO)1

JOB CARD Sales Order:


JC NO305506489

OWNER IS COMFORT TRANSPORTATION PTE LTD OWNER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO.: SH 8884X	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 25.02.2022 11:35
	YR OF MANU. 30.09.2020	TARGET DATE
DUNT CARD NO.	CHASSIS CODE KMHC851CVLU189691	COMPLETION DATE/TIME:

JOB DESCRIPTION

Incident Date: 25.02.2022
 ATURE: 3P.25.02.2022

NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SH 8884X

JU NTUC

Vehicle No.:

SH 8884X

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Netel-CPLP

Date: 25.02.2022
Time: 15:00:58
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305506489
REGN NO : SH 8884X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 25.02.2022 11:35
ACCIDENT DATE : 25.02.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0573-G	PANEL-FENDER RH#	1	588.80	20.00	471.04	DT
0002 04-01-0104-3913-G	EMBLEM-BLUE DRIVE RH	1	26.60	20.00	21.28	nec
0003 04-01-0104-0592-G	PANEL ASSY-FRONT DOOR RH#	1	1,797.20	20.00	1,437.76	DT
0004 04-01-0104-0595-G	PANEL ASSY-REAR DOOR RH#	1	1,789.90	20.00	1,431.92	Xr
0005 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	10.00	67.50	nec
0006 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00	nec

SUB-TOTAL : 3,501.50

JOB NATURE

0000 PB	PANEL BEATING	900.00	700
0001 SP	SPRAYPAINT CHARGE	1200.00	750
0002 20-05	RENEW ADVERTISMENT STICKER-FENDER	100.00	nec
0003 20-05	RENEW ADVERTISMENT STICKER-DOOR	200.00	nec
0004 20-05	RENEW ADVERTISMENT STICKER-REAR	100.00	me

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P.T.O

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 25.02.2022
Time: 15:00:58
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305506489
REGN NO : SH 8884X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 25.02.2022 11:3
ACCIDENT DATE : 25.02.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0005 L TRANSFER DOOR PART

240.00 120

SUB-TOTAL : 2,740.00

TOTAL : 6,241.50

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thuan

82235769

25/2/22 1715

P/p bfr part photo

3 days up

INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

SJS5932J

Date of Accident

25/02/2022 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance NTUC Income Insurance Co-op...

Period of Insurance 25/08/2021 - 24/08/2022

Requested By Por Moy Juan (COMFORTDELG...

Requested Date 25/02/2022 13:05

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

SM 884X