			ENGINEERING				
says integrals	Our Job Ref No :	305506381			ofortDelGro Engineering Pte Ltd		
	Date :	26/02/22		59 L	oyang Drive Singapore 508969 6546 8156		
From	FINALIZATION FORM						
Estimated Cost:	To :		Fax:				
OD/TP/WS/	Attn : Mr	Thevan					
To Inspect Vel	Vehicle Reg No. : Sh	ID7249M CTPL			23/02/2022		
of Morkshop II	The survey and estimates	of the repairs of the above-m	entioned vehicle	e are as follows	3:-		
	The repair job shall bill to:		NTUC	•••	SMF4174U		
nsured:	2. The finalized amount shall be:						
Policy No.	(a) Spare Parts	after List discount					
Cinims No.	(b) Labour Charg	ges					
Sum Insured	Total for Par	t-By-Part Repair Cost			\$0.00		
(Client's R Make of Vo							
NONC OF TO		pair (if applicable) psum repair cost after Less:	20%				
10-line C		um Repair cost			\$2,250.00		
(Policy C Remark: 1							
(Cition.	2 Fatimated	ded for explan	3 wo	orking days.			
Bal. or N	 Estimated normal pe 	-					
DAC AC	 We shall treat the all working days 	bove amount as Correct and	d Confirmed if	there is no re	ply from you within 7		
SIA / F	We are first the estimates and						
si. Re	5. Thank you for your as	finalized amount					
um St		X					
		/\	-				
CA (Signature :	Signature:Name : Thevan					
ale.	Name : Ms. Loke		15/2/77				
Dal	Tel : <u>621483</u>	Da	ite :	173126			
	Fax : <u>6546818</u>	56					
	For Official Use Only						
			Document	Confirm By	Demorks		
-	Item	Amount	Attached Yes or No	(Signature)	Remarks		
-	Rental Rate P/Day		YES	1,32			
-	2. Loss of Income Paid		NO				
	3. Survey Fees						
	4. LTA Search Fee	\$7.49 / \$2.00			N N		
	Medical Fees (on behalf of driver, if applicable)						
	6 Overrun						
	Remarks:	-					

TOTAL DE LA EMPERANTE DE SERVICE DES

The man included and the control of the control of

man for a

The same of the sa

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7249M

Make

: Toyota

Model

: Prius (G4A)

Date: 24.02.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER			\$499.90
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER LOWER COVER		1	\$552.60
1	REAR BUMPER TOWING COVER			\$82.70
1	REAR BUMPER SIDE RETAINER RH			\$94.80
1	REAR BUMPER REINFORCEMENT			\$318.80
1	REAR BUMPER SIDE EXTENSION RH			6140 40
1	REAR BUMPER ARM ASSY RH			\$148.40
1	BACK DOOR GARNISH SUB ASSY			\$889.70
1 1	REAR TRUNK LID LOGO (PRIUS)			\$60.80
1 6	REAR TRUNK LID LOGO (HYBRID)			\$52.40
1 F	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90
	SUB TOTAL			\$2,914.60
	LESS 25%			\$728.65
	DISCOUNTED TOTAL			\$2,185.95
400	EAR TRUNK LID COMFORT & TEL NO. STICKER		-10%	\$60.00
			-10%	\$40.00
	EAR TRUNK LID APPS STICKER		1070	\$50.00
	EAR BUMPER RUBBER MAT		-10%	\$135.70
1/RE	EAR REVERSE SENSOR		-10%	\$285.70
			Ī	\$200.70
Lai	bour Charge			4000.00
	NEL BEATING	1		\$900.00
SP	RAY PAINTING CHARGE	- 1		\$750.00
СН	ECK ALL LIGHTING			\$60.00
TUF	FF KOTE	- 1		\$80.00
REI	MOVE/REFIX REVERSE SENSOR		L	\$60.00
	TOTAL LABOUR		-	\$1,850.00
	ESTIMATE TOTAL			\$4,321.65
1		i		

This is an initial estimate based on a visual inspection of the above vékièle ராகரின் செயின் முன்ற will be prepared after the vehicle is surveyed by a motor Surveyor appointed by their this titan to leave the survey before a surveyed by a motor Surveyor appointed by their this titan to leave the survey before a surveyed by a motor Surveyor appointed by their this titan to leave the surveyed by a motor Surveyor appointed by their this titan to leave the surveyed by a motor Surveyor appointed by their this titan to leave the surveyed by a motor Surveyor appointed by their this titan to leave the surveyed by a motor Surveyor appointed by their this titan to leave the surveyed by a motor Surveyor appointed by their this titan to leave the surveyed by the the survey

Theyan 82235769 24/2/27 1700 LIS 3days wp br after repair photo

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Wilhout Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: