

Business Registration No. 53055563L GST Registration No. M2-0000551-1

Fax : 6477 7398



ESTIMATE



Estimate No. BG 5332	Date Estimated 09/03/2022	Page No. 1 of 1
	Prepared By Andy Ooi Lee Keong	

ESTIMATE REPAIR FOR	ACCOUNT 14356
Ang Soh Khim Blk 454 Clementi Ave 3 #04-550 Singapore 120454	MS First Capital Insurance Limited 35 Robinson Road #16-01 City House Singapore 068877

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH4066A	WF0DXWPCDGC81948	02/11/2016	Mon 2.0 4Dr	127681

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM AGAINST - MS FIRST CAPITAL (SHF253K) DOA.08/01/2022	0.00
TO REMOVE AND REPLACE REAR BUMPER WITH ATTACHMENT.	1200
TO SPRAY PAINT REAR BUMPER.	600
TO RE-CONNECT ELECTRICAL WIRING AT THE REAR SECTION AND CHECK.	150.00
TO CONDUCT ECU RE PROGRAMMING AND TO CLEAR FAULT CODE.	600.00
Total Labour 1:	3,150.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
DS7317K835KAX WAA	BUMPER ASSY - REAR, PRIMED repair	1	2,115.00	10.00	1,903.50
DS7317E911ME5 UAW	MOULDING-FOG LIGHT REAR BUMPER X n	1	620.00	10.00	558.00
DS7317A894MGX WAA	RR BUMPER - LOWER EXTENSION, PRIMED repair	1	670.00	10.00	603.00
DG9317970DC	RR REINFORCEMENT X n	1	750.00	10.00	675.00
DS7317E899BC	RR BUMPER ISOLATOR X n	1	275.00	10.00	247.50
	SENSOR -PARKING AID SYSTEM X n	2	95.00	10.00	171.00
Total Parts :					4,158.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third-party survey is on "Win/lose/Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Customer Name & Signature / Company Stamp

Date _____

Labour 1	S\$	3,150.00
Parts	S\$	4,158.00
Labour 2	S\$	0.00
Excess	S\$	0.00
Total GST @ 7%	S\$	511.56
Grand Total	S\$	<u>7,819.56</u>