

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum
less 20%

Not Attached
11pm 83950h
Paying After Paint
3 days

List Price

BMW less 5%

SLN 2364X

BMW 216D

Parts

frt Bumper	901.75	Tr	980	✓
frt Bumper BMW Badge		Mr	68	✓
frt Bumper Radiator chrome grille @ \$165 X 2pcs		nd/cm	330	✓
frt Bumper Radiator chrome grille holder @ \$120 X 2pcs		MS mgmt	240	✓
frt Bumper Lower centre grille		nd/cm	185	✓
frt Bumper PDC sensor @ \$328 X 4pcs	c198.00	nec	1312	✓
frt Bumper fog lamp LHS		h	303	X
frt Bumper fog lamp chrome LHS		nd	125	✓
frt Bumper fog lamp chrome holder LHS		mgmt	118	✓
frt Bumper no plate garnish		cm	89	✓
frt Bumper side holder LHS		nd	88	✓
frt Bumper sponge		Br	98	✓
frt Bumper reinforcement		n	720	X
frt Bumper PDC sensor wire harness		sn		X
frt Headlamp LHS	2363.65	10f	2364	✓

Special nett items

nett price

front license plate with holder

LKK Auto Consultants hence notify the Repairer of the following:

nd \$50 455m

front Bumper clips (1set)

• To resurvey before/after spray painting

nd \$40 ✓

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on "without prejudice" basis

• No illegal modification allowed

• Supplement is item(s) not covered and is subject to final approval from Insurance Company.

Labour charges

1) To Renew & repair front portion of vehicle

Acknowledged by Repairer:

\$800 3001

Signature:

Date:

2) To spray paint Accident area

\$500 2801

3) To check with BMW computer. scan & clear all fault code

\$300 1006