

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIANZ INSURAN	NCE SINGAPORE PTE LTD	Ref:	CS/AIS22002225/Evy3q2	
	79 ROBINSON RO #09-01 SINGAPOR		Date:	18/08/2022	
			Code:	AIS	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 3324A	Veh. Inspected	SNB 8258U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	AMMAISCL2022-00034fq	Excess (\$)	0.00	
	Assign From	SHANTI	Assign Date	09/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ CLA180	c.c	1332	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	W1K1183842N245322	Colour	BLACK	
	Odometer	5999 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R18	BRIDGESTONE	5 mm	
	L/H Front Tyre	225/45 R18	BRIDGESTONE	5 mm	
	R/H Rear Tyre	225/45 R18	BRIDGESTONE	5 mm	
	L/H Rear Tyre	225/45 R18	BRIDGESTONE	5 mm	
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/03/2022	Inspection Date	17/05/2022	
	Survey held at	CYCLE & CARRIAGE INDUSTR	IES PL		
		188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				