



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SNB8258U

Ms Phane

1 Gateway Drive  
#15-08 Westgate Tower  
Singapore 608531  
Attn: Ms Phane Ai Lang  
Mobile: +6568498379

## Vehicle & Document Information

WIP No 55407  
Reg No/Reg Date SNB8258U / 16/09/2021  
Date In/Mileage / 0  
Chassis No W1K1183842N2453228  
Engine No 28291480671954  
Make/Model MB/CLA 180 COUPE  
Colour/Trim 021 191 Cosmos Blac/ 041 111 Leather Bla

| Account No                                                                    | Terms | Date/Time Printed | CSE | Operator               | Qty  | Unit Price | Disc% | Amount  |
|-------------------------------------------------------------------------------|-------|-------------------|-----|------------------------|------|------------|-------|---------|
| C5M00128                                                                      | Cash  | 07/03/2022/ 10:44 |     | 305 / Alan Quek Ai Lun |      |            |       |         |
| Description of Goods / Services                                               |       |                   |     |                        | Qty  | Unit Price | Disc% | Amount  |
| M BPNSUN                                                                      |       |                   |     |                        |      |            |       |         |
| POLICY NO/ACC DATE : 7990000103 // 04-03-2022                                 |       |                   |     |                        |      |            |       |         |
| DRIVE IN: 05-03-2022 // TP CAR NO: SMH3324A (ALLIANZ INSURANCE)               |       |                   |     |                        |      |            |       |         |
| DATE IN/DATE SURVEY:                                                          |       |                   |     |                        |      |            |       |         |
| BY/AUTHORIZED ON :                                                            |       |                   |     |                        |      |            |       |         |
| A BPILAB                                                                      |       |                   |     |                        |      |            |       |         |
| USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT    |       |                   |     |                        |      |            |       |         |
| S BPNSUB                                                                      |       |                   |     |                        |      |            |       |         |
| SUPPLY & TRANSFER 1PC REAR LEFT RIM                                           |       |                   |     |                        |      |            |       |         |
| PURCHASE ORDER NO:                                                            |       |                   |     |                        |      |            |       |         |
| A BPILAB                                                                      |       |                   |     |                        |      |            |       |         |
| INSPECT & CONDUCT WHEEL ALIGNMENT.NETT                                        |       |                   |     |                        |      |            |       |         |
| A BPILAB                                                                      |       |                   |     |                        |      |            |       |         |
| TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT                  |       |                   |     |                        |      |            |       |         |
| A BPILAB                                                                      |       |                   |     |                        |      |            |       |         |
| REMOVE & REPLACE FRONT LEFT DOOR & REPAIR REAR LEFT DOOR AND REAR LEFT FENDER |       |                   |     |                        |      |            |       |         |
| A BPIRES                                                                      |       |                   |     |                        |      |            |       |         |
| RESPRAY FRONT LEFT DOOR, REAR LEFT DOOR & REAR LEFT FENDER                    |       |                   |     |                        |      |            |       |         |
| M LH/F DOOR SHELL                                                             |       |                   |     |                        | 1.00 | 1756.67    | 00.00 | 1756.67 |
| M LH/F DOOR INSULATION                                                        |       |                   |     |                        | 1.00 | 21.36      | 00.00 | 21.36   |
| M LH/F DOOR SEALING RAIL                                                      |       |                   |     |                        | 1.00 | 104.89     | 00.00 | 104.89  |
| M LH/F DOOR WEATHERSTRIP                                                      |       |                   |     |                        | 1.00 | 306.29     | 00.00 | 306.29  |
| M LH/R DISC WHEEL                                                             |       |                   |     |                        | 1.00 | 710.38     | 00.00 | 710.38  |
| M LEFT WING MIRROR ASSEMBLY                                                   |       |                   |     |                        | 1.00 | 868.19     | 00.00 | 868.19  |

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Steve (LKK)  
17/5/22, 11.30  
6 yr  
WIP  
PIP

Confirmed & accepted by the Repairer of the following:

- To survey before/after spray painting
- To survey damaged part(s) during resurvey
- To survey and confirm to confirmation

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Nett 9,947.78  
7% GST on 9947.78 696.34  
Total Payable 10,644.12

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg