



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNB8258U

Finalization

Allianz Insurance Singapore Pte.
Ltd
79 Robinson Road
#09-01 Spore 068897

6395 3809

Steve

Vehicle & Document Information

WIP No 55407
Reg No/Reg Date SNB8258U / 16/09/2021
Date In/Mileage 17/05/2022/ 5999
Chassis No W1K1183842N2453228
Engine No 28291480671954
Make/Model MB/CLA 180 COUPE
Colour/Trim 021 191 Cosmos Blac/ 041 111 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator			
CTP00001	Cash	27/07/2022/ 18:29		305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 7990000103 // 04-03-2022
DRIVE IN: 05-03-2022 // TP CAR NO: SMH3324A (ALLIANZ INSURANCE)
DATE IN/DATE SURVEY: 17-05-2022 // LKK STEVE
BY/AUTHORIZED ON : FLORA QUEK // 28-04-2022

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

A BPILAB

TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT

A BPILAB

REMOVE & REPLACE FRONT LEFT DOOR & REPAIR REAR LEFT DOOR AND REAR LEFT
FENDER

A BPIRES

RESPRAY FRONT LEFT DOOR, REAR LEFT DOOR & REAR LEFT FENDER

X LH/F DOOR SHELL

1.00 1756.67 00.00 1756.67

X LH/F DOOR INSULATION

1.00 21.36 00.00 21.36

X LH/F DOOR WEATHERSTRIP

1.00 313.32 00.00 313.32

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 6,851.35
7% GST on 6851.35 479.59

Total Payable 7,330.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG