



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNB8258U

Ms Phane

1 Gateway Drive  
#15-08 Westgate Tower  
Singapore 608531  
Attn: Ms Phane Ai Lang  
Mobile: +6568498379

### Vehicle & Document Information

WIP No **55407**  
Reg No/Reg Date **SNB8258U / 16/09/2021**  
Date In/Mileage **0**  
Chassis No **W1K1183842N2453228**  
Engine No **28291480671954**  
Make/Model **MB/CLA 180 COUPE**  
Colour/Trim **021 191 Cosmos Blac/ 041 111 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	07/03/2022/ 10:44		305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

<p>M BPNSUN POLICY NO/ACC DATE : 7990000103 // 04-03-2022 DRIVE IN: 05-03-2022 // TP CAR NO: SMH3324A (ALLIANZ INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :</p>				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
S BPNSUB SUPPLY & TRANSFER 1PC REAR LEFT RIM PURCHASE ORDER NO:				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT				480.00
A BPILAB REMOVE & REPLACE FRONT LEFT DOOR & REPAIR REAR LEFT DOOR AND REAR LEFT FENDER				1920.00
A BPIRES RESPRAY FRONT LEFT DOOR, REAR LEFT DOOR & REAR LEFT FENDER			0.02	2800.00
M LH/F DOOR SHELL	1.00	1756.67	00.00	1756.67
M LH/F DOOR INSULATION	1.00	21.36	00.00	21.36
M LH/F DOOR SEALING RAIL	1.00	104.89	00.00	104.89
M LH/F DOOR WEATHERSTRIP	1.00	306.29	00.00	306.29
M LH/R DISC WHEEL	1.00	710.38	00.00	710.38
M LEFT WING MIRROR ASSEMBLY	1.00	868.19	00.00	868.19

**Alan Quek**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 9,947.78**  
**696.34**

Authorized signatory and company stamp

**Total Payable 10,644.12**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg