

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Billy Tan

Date: 25 Mar 2022

## **Preliminary Advice**

|                    |                                                                                                         |                         |              |
|--------------------|---------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured            | : SKK9940P                                                                                              |                         |              |
| Vehicle No         |                                                                                                         |                         |              |
| TP Vehicle No      | : SLD2585C                                                                                              | Accident Date           | : 01/03/2022 |
| Make               | : TOYOTA ALLION A15                                                                                     | Assignment Date         | : 09/03/2022 |
| Date of Inspection | : 09/03/2022                                                                                            | Est. Duration of Repair | : 12         |
| Inspection At      | : TRUST AUTOWORKS - ANG MO KIO (HQ)<br>BLK 5035, #01-345 ANG MO KIO INDUSTRIAL PK 2<br>SINGAPORE 569538 |                         |              |

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 17,295.32 |
| Revised Amount              | :S\$ | 11,533.00 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 11,533.00 |

Lump Sum Repair :S\$

## **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |

|                   |      |
|-------------------|------|
| Salvage Value     | :S\$ |
| Margin for Repair | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.