

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH7557Y

Make : HYUNDAI

Model : IONIQ(G2)

Date: 07/03/22

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			Ry \$459.40
10	REAR BUMPER CLIPS			nn x \$22.00
1	REAR BUMPER SIDE BRACKET LH			nn x \$55.80
1	REAR BUMPER CENTRE MOULDING ASSY			nn x \$451.25
1	REAR BUMPER REFLECTOR LAMP LH			nn x \$41.45
	<b>SUB TOTAL</b>			\$1,029.90
	<b>LESS 20%</b>			\$205.98
	<b>DISCOUNTED TOTAL</b>			<b>\$823.92</b>
	REAR FENDER ADVERTISEMENT LOGO LH			new \$100.00
	REAR FENDER ADVERTISEMENT LOGO RH			new \$100.00
	REAR BUMPER RUBBER MAT		200	nn x \$50.00
				<b>\$250.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			350 \$600.00
	SPRAY PAINTING CHARGE		630	250 \$300.00
	REMOVE/REFIX REVERSE SENSOR			30 \$80.00
	<b>TOTAL LABOUR</b>			<b>\$980.00</b>
	<b>ESTIMATE TOTAL</b>		\$830 x 02 days	<b>\$2,053.92</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749  
 up 7/3/22 2445  
 02 days  
 Resurvey after repair  
 Tanpin @ Chhandan

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: