

SJF1398X 2007 July.

TP ALG.

Porsche Cayenne 3598cc

Genlin.

WP1ZZZ9PZ8LA04247

Rear Bumper Dehd 1950 ✓ 1678

Rear Bumper clips. M 50 ✓

Rear Bumper Side Holder x 02 <sup>M</sup> 95 x 2 = 190 X

Rear Bumper lower Garnish. Guld 960. ✓ 825

Rear Bumper Diffuser Dehd 1550 ✓

Rear Bumper Tow Cover XM 85 X

Rear Bumper Reinforcement M 1287 X

Rear Bumper Sponge. Guld 158 ✓

Reverse Sensor x 06 <sup>3 pieces</sup> 355 x 6 = 2130 1065  
dngd

Reverse Sensor Holder x 06 20 x 6 = 120. ✓

M ✓

5833

5267.70

STF1398X.

Panel Beating

Spry Painting

Wiring

To remove reverse sensor

To perform diagnostic test.

~~500~~ 300

~~500~~ 250

~~100~~ 30

760

~~120~~ 80

~~250~~ 120

total: 6027.70

L/S: 48K

03 Days.

48K

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: