



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22002246/Tqy3e2	
			Date: 15/06/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKV 8929Y	Veh. Inspected	SMN 3185C
	Policy No.	SP2000584197	Coverage (\$)	0.00
	Claim No.	2022 22004141SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	09/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTEZB3GHX0J004626	Colour	WHITE
	Odometer	128882 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/03/2022	Inspection Date	10/03/2022
	Survey held at	GALAXY AUTO CARE PTE LTD 13 KAKI BUKIT ROAD 4 #01-23 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	