

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 12/12/2021 11:20 (SGT)  
Date of Accident ..... 10/12/2021 18:20 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... Opposite Esso Petrol Station, 650 Dunearn Road  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLK6263T

#### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... R&R CAR RENTAL  
Company Reg No .....  
Email Address .....  
Mobile Phone No ..... (Phone) +6  
Alternative Phone No ..... +65

#### VEHICLE PARTICULARS

Manufacturer ..... Volkswagen  
Model ..... Jetta  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Reporting only  
Vehicle Category ..... Commercial vehicle  
Transmission ..... Auto  
CC ..... 1400

#### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... ThirdParty  
Fleet Policy ..... Yes  
Policy Number ..... 5110777060-02  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... ANIL SINGH S/O DARSHAN SINGH @ MUHAMMAD ZA'IM BIN ABDULLAH ANIL

NRIC No .....	[REDACTED]
Date Of Birth .....	[REDACTED]
Occupation .....	Indoor
Date Of Driving Pass .....	[REDACTED]
Driving experience .....	[REDACTED]
Gender .....	Male
Mobile Number .....	(Phone) [REDACTED]
Alt. Phone Number .....	-
Email Address .....	[REDACTED]
Address .....	[REDACTED]
Address complement .....	[REDACTED]
Postcode .....	[REDACTED]
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Hirer
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Chain Collision
Weather Conditions .....	Raining
Road Surface .....	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	3
Was anybody injured in the Accident? .....	Yes
Was any injured conveyed to hospital by ambulance? .....	No
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No

#### PASSENGER 1

Name .....	DANI AYATOLLAH BIN ZAIM
Gender .....	Male

#### PASSENGER 2

Name .....	NASHA INSYIRAH
Gender .....	Female

#### PASSENGER 3

Name .....	JAMIAH BTE MAMOOD
Gender .....	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

1 = SLK6263T 2 = SLS8247K 3 = UNKNOWN WAS RAINING HEAVILY AND HIRER DID NOT MANAGE TO CAPTURE THE 3RD CAR PLATE, HOWEVER LICENCE DETAILS WAS EXCHANGED

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	Yes
Reasons for not uploading a video of the accident .....	not provided

Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ..... SLS8247K  
Vehicle Manufacturer ..... -  
Vehicle Model ..... -  
Vehicle Variant ..... -  
Vehicle Colour ..... -  
Vehicle Category ..... Private car  
Name of Driver ..... VIKNESVARAN S/O DANABALAN  
NRIC No .....   
Contact Number ..... -  
Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number ..... UNKNOWN  
Vehicle Manufacturer ..... -  
Vehicle Model ..... -  
Vehicle Variant ..... -  
Vehicle Colour ..... -  
Vehicle Category ..... Private car  
Name of Driver ..... -  
Contact Number ..... -  
Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person ..... NASHA INSYIRAH  
Gender ..... Female  
Phone No ..... (Phone) +6   
Address ..... -  
Address Complement ..... -  
Post Code ..... -  
Approximate Age Years Old ..... -  
Injuries Sustained ..... -  
Injured person in which vehicle? ..... SLK6263T  
Were seat belts worn? ..... -  
Was this injured conveyed to hospital by ambulance? ..... No

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

R&R CAR RENTAL

11-12-2021 08:47:01 PM

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) /Date & Time

Witnessed by Reporting Centre Personnel

Page 1 of 2

### Sketch Plan



### Describe Circumstances of the Accident

1 = SLK6263T

2 = SLS8247K

3 = UNKNOWN WAS RAINING HEAVILY AND HIRER DID NOT MANAGE TO CAPTURE THE 3RD CAR PLATE, HOWEVER LICENCE DETAILS WAS EXCHANGED

### Declaration

I/We declare the foregoing particulars are true in every respect.

R&R CAR RENTAL

11-12-2021 08:47:01 PM

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder)  
/Date & Time

Witnessed by Reporting  
Centre Personnel

Page 2 of 2



















**PRO  
PLUS  
AUTOMOBILE  
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928  
Tel: +65 6707 8932 Fax: +65 6352 6802  
Mobile: +65 9673 0595 / +65 9788 9809  
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com  
Company Registration No: 40158500M

*Consultants to Motor Industry, Automobile  
Engineers, Claims Investigators, Accident  
Reconstruction Specialists, Insurance Loss  
Assessors / Adjusters, Valuers And  
Licensed Appraisers.*

G8/20/5549/CHH/JP/SL

To:

M/s R & R Car Rental  
c/o 143 Bukit Timah Road  
Singapore 229843

INVOICE NO  
OUR REFERENCE  
YOUR REFERENCE  
DATE


: 800141  
: PP/ET/ST.6263.TP.12-21  
:  
: 27 December 2021

VEHICLE REGISTRATION NO : SLK6263T  
VEHICLE MAKE/MODEL : Volkswagen Jetta 1.4 TSI

- ☒ TO INSPECTION/APPRaisal FEES
- ☐ TO AFFIRM AFFIDAVIT
- ☐ TO COURT ATTENDANCE ON
- ☐ TO REINSPECTION FEES
- ☒ TO PHOTOGRAPHY
- ☒ TO TRANSPORTATION CHARGES & FOLLOW-UP REINSPECTION

- ☐ OTHERS (SPECIFY)
- ☐ SINGAPORE DOLLARS: SEVEN HUNDRED AND SEVENTY-FOUR ONLY

\$774.00







**PRO  
PLUS  
AUTOMOBILE  
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928  
Tel: +65 6707 8932 Fax: +65 6352 6802  
Mobile : +65 9673 0595 / +65 9788 9809  
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com  
Company Registration No : 40156500M

*Consultants to Motor Industry, Automobile  
Engineers, Claims Investigators, Accident  
Reconstruction Specialists, Insurance Loss  
Assessors / Adjusters, Valuers And  
Licensed Appraisers.*

Our Ref : PP/ET/ST.6263.TP.12-21

27 December 2021

M/s R & R Car Rental  
c/o 143 Bukit Timah Road  
Singapore 229843

**WITHOUT PREJUDICE**

Dear Sir,

**Re: Third Party Claim  
Vehicle Registration No. : SLK6263T**

We refer to your instruction to appraise the above-mentioned vehicle on 15 December 2021.

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by **Boss Garage** for **S\$9,682.00** as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is **S\$3,843.50**. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for **S\$3,100.00 NETT** which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of **4 (four) days**, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.


Very truly yours,

**PRO PLUS AUTOMOBILE ENGINEERS**

  
**Errol Tan**

**Licensed Appraiser & Automobile Engineer**

Encls:



This information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please, contact us immediately by telephone so that we can arrange for its return.



**PRO  
PLUS  
AUTOMOBILE  
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928  
Tel: +65 6707 8932 Fax: +65 6352 6802  
Mobile : +65 9673 0595 / +65 9788 9809  
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com  
Company Registration No : 40156500M

*Consultants to Motor Industry, Automobile  
Engineers, Claims Investigators, Accident  
Reconstruction Specialists, Insurance Loss  
Assessors / Adjusters, Valuers And  
Licensed Appraisers.*

**VEHICLE INSPECTION REPORT**

To: M/s R & R Car Rental  
c/o 143 Bukit Timah Road  
Singapore 229843

Insured :  
Policy Number :  
Claim Number :  
Our Reference : PP/ET/ST.6263.TP.12-21  
Own Damage/Sum Insured :  
Excess :  
Third Party/Insce Company :  
Date : 27 December 2021

Instructed By : Yourself  
Date of Assignment : 15 December 2021  
Date of Accident : 10 December 2021  
Date of Inspection : 15 December 2021  
Name of Workshop : Boss Garage  
Place of Inspection : 143 Bukit Timah Road  
Singapore 229843

**PARTICULARS OF DAMAGED VEHICLE**

Registration Number	: SLK6263T	Odometer Reading	: 153526	Km
Make/Model	: Volkswagen Jetta 1.4 TSI	Radio/Cassette/CD	: Fitted	
Year of Manuf/Reg	: 2012	Air Conditioner	: Fitted	
Engine Number	: CAXB28457	View Mirrors	: Fitted-o/s & n/s	
Chassis Frame Number	: WVVZZZ16ZDM001094	Seat Belts	: Fitted-front & rear	
Class/Type	: Passenger [Saloon]	Other Assessories		
Colour	: Black	(Specify)	: Fitted	

**PRE-ACCIDENT CONDITION OF VEHICLE**

General Condition	: Good	Any Apparent Engine	
Paintwork	: Good	Modification/s	:
Footbrakes	: Serviceable	Market Value	:
Steering	: Serviceable	Scrap Value (PARF/OMV)	:
Undercarriage(Front)	: Serviceable		
Undercarriage(Rear)	: Serviceable		

**TYRE CONDITION ON VEHICLE**



Front (Size)	: 225/40ZR18	NEAR SIDE	OFF SIDE
MAKE	Westlake	70%	70%
Rear(Size)	: 225/40ZR18		
MAKE	Westlake	70%	70%
SPARE (Size)			
MAKE			
Type of Road Wheels	: Alloy		

NOTE: The above percentages represent the estimated remaining life of the tyre threads  
\*Denotes damaged component/s

**IMPACT OF VEHICLE**

Direction of Impact [ → ]

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle, sustaining damages to the rear portion of the vehicle.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

 Damage Area/s

Damages sustained were the bootlid & its inner reinforcement - dented/bent, bootlid inner lock/striker - bent inwards/shifted, rear end panel - thrust inwards/buckled, rear bumper assembly, rear fender o/s & n/s - buckled, rear compartment floor/tyre well panel - buckled, etc.

*Note :* Follow-up reinspection of damaged components & work-in-progress on 18/12/2021.

Follow-up reinspection of vehicle on 21/12/2021 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.

**ESTIMATE**

The estimate submitted by Boss Garage as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairer has agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts	7,182.00	2,633.50	Estimated number of days for repairs: 4
Labour Charges	1,500.00	610.00	
Paint Work	1,000.00	600.00	Number of photographs taken at time of static inspection: 34
Towing Charges			
Others			
<b>TOTAL</b>	<b>9,682.00</b>	<b>3,843.50</b>	

**Remarks:** The repairer has agreed to undertake the repairs on a contract lump sum of S\$3,100.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

**NOTE:** The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, revised amount should be deemed to be valid.



## APPRAISEMENT SCHEDULE

Registration No: SLK6263T

Your Reference: PP/ET/ST.6263.TP.12-21

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate	Revised Amount
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Bootlid	Dented/bent	1,433.00	Repaired
2	1pc	Bootlid 'VOLKSWAGEN' motif	Essential	71.00	71.00
3	1pc	Bootlid 'JETTA' emblem	Essential	58.00	58.00
4	1pc	Bootlid 'TSI' emblem	Essential	31.00	31.00
5	1pc	Bootlid inner lock	Bent/shifted	158.00	Repaired
6	1pc	Bootlid striker	Bent	31.00	Repaired
7	1pc	Bootlid draught weatherstrip	Essential	168.00	168.00
8	2pcs	Taillamp assembly @ \$599.00	Displaced/serviceable	1,198.00	Rejected
9	1pc	Rear end panel	Thrusted inwards/buckled	990.00	Repaired
10	1pc	Rear end panel inner garnish	Warped/serviceable	125.00	Rejected
11	1pc	Rear bumper	Dented/chafed/distorted	1,278.00	1,278.00
12	2pcs	Rear bumper reflector @ \$101.00	Serviceable	202.00	Rejected
13	1pc	Rear bumper lower skirt	Cut/chafed	396.00	396.00
14	1pc	Rear bumper reinforcement	Bent/buckled	395.00	395.00
15	2pcs	Rear bumper side retainer @ \$59.00	Cracked	118.00	118.00
		Less: 10% by PRO+			251.50
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	2pcs	Terostat @ \$80.00	Essential	160.00	120.00
2	1set	Rear bumper clip/fastener	Essential	50.00	30.00
3	1set	Rear bumper reverse sensor	Malfunctioned due to impact	320.00	220.00
<b>Sub-total</b>				<b>7,182.00</b>	<b>2,633.50</b>

## APPRAISEMENT SCHEDULE

Registration No: SLK6263T

Your Reference: PP/ET/ST.6263.TP.12-21

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate	Revised Amount
			B/F	7,182.00	2,633.50
1		<u>LABOUR &amp; MISC. CHARGES</u> To disconnect rear wire harness of electrical components to facilitate repairs, reconnect & check functions including to replace/recalibrate rear bumper reverse sensors to specifications		80.00	50.00
2		To dismantle/transfer/rebuild bootlid fittings/ancillary accessories to new bootlid		150.00	Rejected
3		To dismantle/install rear luggage fittings/ancillary attachments, board, trims, garnishes, spare tyre, tools etc. to facilitate repairs		150.00	60.00
4		To check diagnostics of vehicle management/control units; reset memories to specifications etc	Unnecessary	120.00	Rejected
5		To dismantle/renew the rear accident damaged portions. To heat, knock-out, reshape, straighten, orientate & align bootlid & its inner reinforcement, bootlid inner lock/striker, rear end panel, rear fender o/s & n/s, rear compartment floor/tyre well panel etc. to symmetrical dimensions		1,000.00	500.00
6		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint	}		
7		To do rustproofing and cavities preservation to the replaced and repaired panels	}	1,000.00	600.00
			}		
			<b>Grand - Total</b>	<b>9,682.00</b>	<b>3,843.50</b>

Note: The repairer has agreed to undertake the repairs on a contract lump sum of S\$3,100.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers


**ERROL TAN**

B.A Econ (Hons). UK

Dip. Auto Engr. &amp; Motor Trade Management. UK

Automobile Engineer &amp; Licensed Appraiser

## PRO PLUS AUTOMOBILE ENGINEERS (Inspection photographs)













































Your Ref : SLS 8247K

Our Ref : **JP/SL/SLK 6263T/CHH**

Date : 16 December 2021

Fax : **6538 3708**

Tel : **3152 0985**

Email : **jiapei@kscgp.com**

India International Insurance Pte Ltd

BY EMAIL ONLY

**DATE OF ACCIDENT: 10 DECEMBER 2021**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We are instructed by the owner of SLK 6263T to notify you of a road traffic accident on 10 December 2021 at about 6.20 p.m Opposite Esso Petrol Station, 650 Dunearn Road, involving our client's vehicle registration number SLK 6263T, an unknown number vehicle and vehicle registration number **SLS 8247K** which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

*NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.*

Yours faithfully,

*f SL*

Enc.

Your Ref : SLS 8247K  
Our Ref : **JP/SL/SLK 6263T/CHH**  
Date : 16 December 2021

Fax : **6538 3708**  
Tel : **3152 0985**  
Email : **jiapei@kscgp.com**

India International Insurance Pte Ltd

BY EMAIL ONLY

**DATE OF ACCIDENT: 10 DECEMBER 2021**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/No.	Name of Surveyor	Company Name
1.	Errol Tan	Pro Plus Automobile Engineers
2.	Dave Chang	Sincere Appraisal Services
3.	Lee Kok Weng	Lee Automobile Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Car Hub Holdings Pte. Ltd. (Boss Garage)  
143 Bukit Timah Road  
Singapore 229843

Contact Person/Tel : Jeremy Choy  
Tel: 8777 8055 / 8684 8055

Yours faithfully,

*f SL*

Your Ref : SLS 8247K

Our Ref : **JP/SL/SLK 6263T/CHH**

Date : 16 December 2021

**Acknowledgement**

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of \_\_\_\_\_ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (part by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:



Enquire Vehicle's Insurance Particulars ( As At 10 Dec 2021 / 18:20:00 )

Vehicle No.:

**SLS8247K**

Make Description/Model:

**MAZDA / MAZDA3 SEDAN 1.5 AT EU6**

Insurance Company Name:

**MSIG INSURANCE (SINGAPORE) PTE LTD**

Insurance Company Name:

**INDIA INT'L INS PTE LTD**

Business Transaction Reference No.:

**20211216092232304504**

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).