

⏪

⏩

1 of 2 ?

⏴


⏵

100% ▾

📄 ✓

🖨

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/GRB21010730	
INDIA INTERNATIONAL INSURANCE PL				Ref: CS3/GRB21010730/GRB	
64 CECIL STREET				Date: 16/10/2021 10/03/2022	
#05-02 IOB BUILDING SINGAPORE 049711				Code: GRB	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		SMP 8086L		Veh. Inspected GBK 9499D	
Policy No.				Coverage (\$) 0.00	
Claim No.				Excess (\$) 0.00	
Assign From		DIVYASHNI SUBRAMANIAM		Assign Date 16/10/2021 10/03/2022	
2. Vehicle Particulars & Condition					
Make & Model				c.c 0	
Engine No.		HIDDEN		Year of Reg.	
Chassis No.				Colour	
Odometer		-		Steering	
Brakes				Modification	
General					
3. Conditions of Tyres					
		Size		Make	Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4. Description of Damages					
5. General Information					
Accident Date		16/10/2021		Inspection Date 25/10/2021	
Survey held at		160 Sin Ming Drive #02-09 Autocity			
Repairer		833 MOTORSPORTS			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					