

ASS. REC. BY:

REF:

AG2/ 220022471KV

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Chen Guan  
 of \_\_\_\_\_  
 Insured: SLJ 7092T  
 Policy No. \_\_\_\_\_  
 Claims No. C1001416/JM  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 06 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: PMG 6920R Yr Regn: 12, 18  
 Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Skoda Superb c.c. 1984  
 Colour: M. Gray A/C: Insured / Std / NI / NA  
 Sp. Reading: 104349 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: TMB BD 7NP 6K 702 1893  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod:  Nil / S/Rim / STD / A/Rim or \_\_\_\_\_

Tyre Size: F: 235/40ZR19  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Windforce

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>8</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>8</u> mm
D.O.A. <u>4/3/22</u>	D.O.I. <u>10/3/2022</u>

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S FR body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/5/23	Submit preli report-revised fig \$1585 check items \$1050
	Note: Last conversation with repairer on 16.5.23 still pending for parts prices

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: \_\_\_\_\_

1)

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

Transportation:

: Interview (\$ \_\_\_\_\_)

\_\_\_\_\_ S + RS \_\_\_\_\_ SI

: Tech Invs (\$ \_\_\_\_\_)

Fuel

: Weekend (\$ \_\_\_\_\_)

Others

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not with work  
 11 Rm @  
 Parkway After Paing  
 6 day*

To: Auto & General Insurance (S) Pte Ltd

Third Party

Policy No: \_\_\_\_\_

08.03.2022

Date: \_\_\_\_\_

Accident Date : 04.03.2022

Specialised in Car Painting, Welding,  
 Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
<b>Estimate Cost of Repair to "Skoda Superb" Reg. No. SMG6920P                      Claiming Against Your Insured Veh. No. SLJ7092T</b>			
1pc	Front Bumper <i>Be</i>		-
10pcs	Front Bumper Clips <i>me</i>		-
1pc	Front Bumper Corner Retainer LH <i>0.1</i>		-
1pc	Front Bumper Reinforcement <i>21</i>		-
1pc	Front Bumper Sponge LH <i>su x</i>		-
1pc	Front Bumper Core Shuttle <i>su x</i>		-
1pc	Front Bumper Parking Sensor LH <i>su x</i>		-
4pcs	Front Bumper Parking Sensor Holders <i>su x</i>		-
1pc	Front Bumper Fog Lamp LH <i>su x</i>		-
1pc	Front Fender LH <i>Be</i>		-
1pc	Front Fender Shield <i>cm</i>		-
10pcs	Front Fender Shield Clips <i>me</i>		-
1pc	Front Wheel Rim LH <i>ad</i>		-
1pc	Front Shock Absorber <i>?</i>		-
1pc	Front Knuckle Arm <i>?</i>		-
1pc	Front Knuckle Arm Bearing <i>?</i>		-
1pc	Front Lower Arm <i>?</i>		-
1pc	Front Lower Arm Ball Joint LH <i>?</i>		-
1pc	Front Lower Arm Bracket LH <i>su x</i>		-
1pc	Front Bearing Hub <i>?</i>		-
1pc	Front Steering Rack <i>su x</i>		-
1pc	Front Steering Tie Rod LH <i>su x</i>		-
1pc	Front Steering Tie Rod End LH <i>su x</i>		-
1pc	Headlamp LH (LED) <i>su x</i>		-
1pc	Front Door Wing Mirror LH <i>cm</i>		-
1pc	Front Door Wing Mirror Cover LH <i>?</i>		-
1pc	Front Door Wing Mirror Signal Lamp LH <i>cm</i>		-
1pc	Front Door Wing Mirror Glass LH <i>cm</i>		-
1pc	Front Door Glass LH <i>cm</i>		-
1pc	Front Door Glas Outer Moulding LH <i>ad</i>		-
	Less 5%		-
	Front Door Glass Solar Film		<i>me</i> 180.00 SN 6000
	To Conduct Electrical Check, Focus Headlamp		30.00 <i>156</i>
			<b>210.00</b>

C/F

210.00

Date  
 11  
 Date  
 21  
 Repr  
 Lump



# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Auto & General Insurance (S) Pte Ltd  
 \_\_\_\_\_  
 \_\_\_\_\_  
**Accident Date : 04.03.2022**

Policy No: Third Party  
 \_\_\_\_\_  
 Date: 08.03.2022

Specialised in Car Painting, Welding,  
 Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	<b>Estimate Cost of Repair to "Skoda Superb" Reg. No. SMG6920P                      Claiming Against Your Insured Veh. No. SLJ7092T</b>		
		B/F	210.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60.00 <i>3rd</i>
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		250.00 ?
	To Conduct Computerize Wheel Alignment Test		80.00 <i>6th</i>
	To Conduct High Speed Balancing		80.00 <i>2nd</i>
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, Bonnet, Front N/S Door, Rear N/S Door & Part Replacement		700.00 <i>500</i>
	To Respray Affected Areas		1,300.00 <i>900</i>
	To Reseal Paint Protection (Diamond rite) to Spray Paint Areas		<i>(B/F)</i> 800.00 ?
	<b>Total :</b>		<u><u>3,480.00</u></u>

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 04/03/2022 10:10 (SGT)  
Date of Accident ..... 04/03/2022 09:00 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... MARYMOUNT TOWADS BISHAN  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMG6920P

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... LEOW CHENG KIAT  
NRIC No ..... S1568167E  
Email Address ..... rolandleow@gmail.com  
Mobile Phone No ..... (Phone) +65-81128698  
Alternative Phone No ..... +65-81128698

### VEHICLE PARTICULARS

Manufacturer ..... Skoda  
Model ..... Superb  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private hire  
Transmission ..... Auto  
CC ..... 2000


### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 5119653150-01  
Cover Note Number ..... 28/12/2021 - 27/12/2022

### DRIVER

Name of Driver ..... LEOW CHENG KIAT  
NRIC No ..... S1568167E

SKETCH PLAN



MY VEHICLE WAS TRAVELLING BEHIND VEHICLE B ON THE SLIP ROAD OF MARYMOUNT TOWARDS BISHAN . I WANTED A U-TURN AT THE JUNCTION AHEAD SO I TURNED RIGHT TO THE RIGHTMOST LANE. VEHICLE B AFTER EXIT OUT FROM THE SLIP, GOES INTO THE MIDDLE LANE AND CHANGED LANE ONTO MY ONGOING LANE THUS HIT ONTO MY VEHICLE FRONT LEFT PORTION.

DECLARATION

(We declare the foregoing particulars are true in every respect

4/3/2022 9:46  
 Policyholder's Signature  
 Date & Time

*[Signature]*  
 4/3/2022 9:46  
 Driver's Signature (If driver is not the policyholder)  
 Date & Time:

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name: Chen JunLiang  
 NRIC/ Fin No: S990765