



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0168/2022/KS
DATE : 8-Mar-22
WIP : 14794

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

5-Sep-22

OWNER'S NAME : MS TAN YU PING SHARON
ADDRESS : BLK 629 ANG MO KIO AVE 4
#04-1018
SINGAPORE 560629
TELEPHONE : HP +65 98563896
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 19000093882-01
VEHICLE NO : **SML 487 L**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 30/4/2019
ENGINE NO : DAX 052534
CHASSIS NO : WAUZZZFY2K2053589
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Mar-22
PLACE OF ACCIDENT : NEAR 650 AMK AVE6, BLOCK 640 SG 560640
JUNCT OF AMK AVE 6 AND AMK ST 61

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 487 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00		
4	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	\$	500.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	3,000.00	\$	950.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 8,672.00	\$	2,122.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SML 487 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,080.00	\$ 2,504.80
2	FRONT BUMPER FIXING PARTS	1	\$ 338.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 84.00	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 252.00	
5	FRONT BUMPER GRILLE - CENTER	1	\$ 161.00	
6	FRONT BUMPER SPOILER	1	\$ 850.00	
7	FRONT BUMPER UNDERRUN BAR- SELENITE SILVER	1	\$ 580.00	
8	FRONT BUMPER CLOSNG ELEMENT	1	\$ 246.00	
9	RADIATOR GRILLE	1	\$ 3,910.00	\$ 3,128.00
10	"QUATTRO" EMBLEM	1	\$ 111.00	\$ 88.80
11	RADIATOR GRILLE STRIKER PLATE	1	\$ 271.00	\$ 216.80
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,302.00	\$ 1,041.60
13	FRONT BUMPER AIR GUIDE GRILLE END CAP- LH / RH	2	\$ 206.00	
14	FRONT BUMPER LOCKING CLIP	4	\$ 18.00	
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 198.00	
16	FRONT BUMPER EINFORCEMENT BEAM	1	\$ 1,043.00	
17	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	
18	FRONT BUMPER TOP COVER	1	\$ 143.00	
19	"CAUTION" STICKER	1	\$ 16.00	
20	"A/C" STICKER	1	\$ 22.00	
SUB TOTAL SPARE PARTS			\$ 11,917.00	\$ 6,980.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 487 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 6,980.00
21	HORN - LH / RH	2	\$ 416.00	
22	FRONT PARKING AID SENSOR	2	TBC	
23	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	
24	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 606.00	
25	FRONT WHEEL SPOILER - LH / RH	2	\$ 344.00	
26	FRONT WHEEL COVER - LH / RH	2	\$ 1,418.00	\$ 1,134.40
27	HEADLIGHT MOUNTING - LH / RH	2	\$ 264.00	\$ 210.40
28	LED HEADLIGHT - LH / RH	2	\$ 17,416.00	
29	LIFTY CYLINDER - LH / RH	2	\$ 306.00	
30	LIFTY CYLINDER HOSE	1	\$ 145.00	
31	RADIATOR AIR GUIDE - LH / RH	2	\$ 132.00	
32	RADIATOR AIR GUIDE - CENTER	1	\$ 48.00	
33	RADIATOR AIR GUIDE - UPPER	1	\$ 55.00	
34	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
35	SUNDRIES	1	\$ 300.00	
TOTAL SPARE PARTS		:	\$ 33,437.00	\$ 8,384.80
TOTAL LABOUR CHARGES		:	\$ 8,672.00	\$ 2,122.00
GRAND TOTAL		:	\$ 42,109.00	\$ 10,506.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-31/08/22



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
[EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT