



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMF8601C Skoda Octavia

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper left side retainer X	\$ 180.00
2	1	Fog lamp LH eyebrow chrome X	\$ 150.00
3	1	Fog lamp chome base cover X	\$ 220.00
4	1	Fog lamp X	\$ 250.00
5	1	Front left fender / DD	\$ 985.00
6	1	Front left fender inner cowling X	\$ 245.00
7	1	Front left fender inner garnish X	\$ 80.00
8	1	Front left suspension assy full set X	\$ 980.00
9	1	Front left control arm X	\$ 780.00
10	2	Front tie rod end and link X	\$ 485.00
11	1	Front right wheel hub with bearing X	\$ 380.00
12	1	Sport rim X CUT	\$ 900.00
13	1	Sport rim cap X	\$ 100.00
14	1	Tyre X	\$ 300.00
			<u>\$ 6,035.00</u>



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMF8601C Skoda Octavia

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips X	\$ 60.00
2	6	Front bumper lower grille clips X	\$ 50.00
3	8	Front bumper side trim clips X	\$ 50.00
4	6	Front fender inner cowling clips X	\$ 30.00
5	8	Front support panel top garnish clips X	\$ 30.00
6	1	Number plate and casing X	\$ 100.00
Special Nett Items			<u>\$ 320.00</u>



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMF8601C Skoda Octavia

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,200.00
2	To putty and spray painting front portion.	\$ 1,500.00
3	To apply anti rust proofing to front left affected area	\$ 120.00
4	To check wiring and focus front headlamp.	\$ 60.00
5	To remove and install front left undercarriage parts.	\$ 350.00
6	To check, remove and replace aircon related radiator, condensor etc, check air-con, top up gas etc	\$ 200.00
7	To balance front wheel.	\$ 120.00
8	To conduct wheel alignment.	\$ 120.00
9	To remove and install front bonnet lock mechanism assy.	\$ 100.00
10	To do reprogramming to remove fault code	\$ 200.00
11	Remove body sticker and replace new sticker	\$ 200.00
Total labour :		\$ 4,170.00

200

250

60

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

3 Days.

P/P

before paint jobs.

Gu. Q. Y

16/3/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: