

NOT Notarized
 11 Rmp @ 3000p
 Resurvey After Repair
 5 days

VEHICLE NO: SKZ8072Y
 CHASSIS NO: ZGE20-6026405

MODEL: TOYOTA WISH

DESCRIPTION	REPAIRER'S ESTIMATE(\$)
<u>PARTS (LIST ITEMS)</u>	
TAILGATE 1272.00	RM \$ 1,400.00 ✓
TAILGATE INNER TRIM	SL \$ 500.00 X
TAILGATE LOCK ASSY	PL \$ 450.00 X
TAILGATE CENTRE GARNISH	PL \$ 200.00 X
TAILGATE LAMP LHS	SL \$ 300.00 X
TAILGATE LAMP RHS	SL \$ 300.00 X
TOYOTA EMBLEM	RM \$ 80.00 ✓
VALVE EMBLEM	RM \$ 80.00 ✓
REAR BUMPER 566.10	BR \$ 600.00 ✓
END PANEL	PL \$ 540.00 X
END PANEL TOP GARNISH 265.60	my D17 \$ 300.00 X
TAILGATE WEATHERSTRIP	SL \$ 320.00 X
	25% \$ 5,070.00
	\$ 1,267.50
	\$ 3,802.50
<u>SPECIAL NETT ITEMS</u>	
REAR BUMPER CLIPS 1 SET	\$ RM 60.00 ✓
WINDSCREEN SEALEANT	\$ RM 40.00 ✓
REAR SENSORS	\$ PL 200.00 X
	Total \$ 300.00
	TOTAL PARTS \$ 4,102.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	600
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	20
4	To provide anti-rust treatment on affected areas	\$ 100.00	60
5	Remove & refit REAR sensor	\$ 100.00	50
6	Transfer tailgate parts	\$ 150.00	60
7	Remove & refit rear windscreen	\$ 150.00	120
	Labour Total :	\$ 3,800.00	
	TOTAL (PARTS & LABOUR):	\$ 7,902.50	