



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21011113/Rqy3s2-1	
			Date: 20/04/2022	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 5854R	Veh. Inspected	FBR 1066K	
Policy No.	D21MFL0000447	Coverage (\$)	0.00	
Claim No.	MFL2021D0004618	Excess (\$)	0.00	
Assign From	Carine Kek	Assign Date	10/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ADV150 ABS CVT	c.c	149	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MH1KF6113KK012789	Colour	MULTI-COLOUR	
Odometer	32854 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80-14	TIMSUN	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/70-13	TIMSUN	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2021	Inspection Date	01/11/2021	
Survey held at	TWO-WHEELED AFFAIR 39 WOODLANDS CLOSE, #03-04, MEGA@WOODLANDS, SINGAPORE 737856			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	