

## **ESTIMATE FOR SMZ9733T**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

CHINA TAIPING INSURANCE (S) PTE LTD

ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

62222366

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No Engine No

Make/Model Colour/Trim

W1N2476842W1206862

28291480530270

Vehicle & Document Information

MB/GLB 180

SMZ9733T

55490

027 775 Iridium Sil/ 041 101 ARTICO Blac

/ 28/05/2021

ccount No	Terms	Date/Time Printed	CSE	Operator				
VC000668	Credit	10/03/2022/ 09:56	ко	301 / Kerlyn Ong	04	Unit Price	Disc%	Amount
		Description of Good	s / Services		Qty	Unit Frice	D13070	
Z REQUEST	- 1-		DI CO	FEIGIAL	TA	YI	$\mathbf{V}$	OICE
	Request	NOLA	NU	FFICIAL			AA	The same of the sa
M BPNSUN	IO /ACC DATE	: GA573781 // 09/03/	/2022					
DRIVE IN		: 10/03/2022 //				1		
	DATE SURVE				150	1		
BY/AUTH		:			712			1920 3840.
A DOTLAD		TANKE DAMACI	D DADTS &	REFINISH. GARXI	1 11			2/04 1000
	MBLE AND RE	PLACE ATTACHED DAMAGE	U PARIS Q	NEI INTOM	11 ~			1699 1800.
A BPIRES	TATICATE 8	REAR BUMPER 962	Re Xo	0 ×2			0.10	380.
				011111			0.10	
USING X	ENTRY DIAGN	NOSTIC TO CHECK ON COL	ITROL UNIT	RESET MEMORY VO				
IDENTIF	ICATION STA	ANDARD. NETT	41	1111/				120.
A BPILAB		NG SYSTEM AND WATER I	ST FOR ANY	LEAKAGE. NETT			0 10	400.
CHECK RI	EAR LIGHTIN	IG STSTEM AND WATER	1 1				0.19	400.
A BPILAB	% TRANSFER	TAILGATE MECHANICAL	ELETRICAL	INSTALL TO				
NEW DOOR	R.NETT	15					0.07	560.
		THE WAR CONTENT WITH	NCTALL N	FTT				
		REAR WINDSCREEN WITH			Sales aga	<b>」)</b>		300.
S BPNSUB	R INSTALL 1	PC REAR WINDSCREEN	OLAR HUPER	OPTIK FILM.NETT	and O			1
PURCHASE	F ORDER NO:	CIL			1 00509	44 491.13	00.00	491.
M REAR BUN	MPER LOWER	TRIM / (W)		1334.62	/1.00	1304.62	00.00	1304.
M REAR BUN	MPER /	(1)		1327-01	1.00	1154.65		1154.
M REAR BUN	MPER LOWER	CHIROTTE 2		1101.30	1.00	11 174.00	00.00	174.
	MPER STEP P WING COVER	OR 1 XII	)			11 44.67	00.00	41.
M RH/ BASI	IC CARRIER	FOR BUMPER	o		1.00	86.92		86.
M RH/ REAF	R BUMPER LA	TERAL SUPPORT		211021	1.00	3040.44	00.00	3040.
M TAILGATE	· / W	COME 1 XI	10	3110-36-	1.00	218.01	00.00	218.
M TAILGATE	SEAL	WY I I	Kerlyn O	ng Kal Li				

Confirmed & accepted by

DID: 6771 4420 HP: 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loc

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes benz com sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 1 of 2





## **ESTIMATE FOR SMZ9733T**

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

LTD

62222366

CHINA TAIPING INSURANCE (S) PTE

ATTN: MOTOR CLAIM DEPARTMENT

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR 8500111-X

Vehicle & Document Information

55490

Reg No/Reg Date

SMZ9733T / 28/05/2021

Date In/Mileage

WIP No

Chassis No.

W1N2476842W1206862

Engine No

28291480530270

Make/Model Colour/Trim

MB/GLB 180

027 775 Iridium Sil/ 041 101 ARTICO Blac

Account No. CSE Operator Date/Time Printed WC000668 301 / Kerlyn Ong Credit 10/03/2022/ 09:56 Amount Unit Price Disc% Qty Description of Goods / Services 856.66 00.00 160.11 00.00 856.66 1.00 REAR WINDSCREEN 320.22 2.00 ONE-COMPONENT ADHESIVE 53.84 53.84 00.00 MERCEDES STAR / NC 3.00 2 2.64 00.00 7.92 GROMMET / 110 85.54 /85.54 00.00 / NIC MODEL PLATE 384.39 384.39 00.00 RH/ OUTER REAR LAMP COMBINATION 384.39 00.00 393.75/384.39 RH/ REAR LAMP COMBINATION / DR 504.07 504.07 00.00 REAR CROSS MEMBER Store CLKK) WM L 17/5/12, 10-30, 010 LKK Auto Consultants hend the Repairer of the following • To resurvey before/after spray p To display damaged partial during resurvey Parts prices are subject in condirmation Third party survey is on a 1/4.1 · Frejudice" basis Supplementary (e.g., 5, pp. 6) be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer

Confirmed & accepted by

Kerlyn Ong Kal Id DID: 6771 4420 HP: 9186 3113

Email : kerlyn.ong@cyclecarringe.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Nett 7% GST on 16552.75

16,552.75 1158.69

**Total Payable** 

17,711.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 2 of 2

