



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
SHASI KUMAAR S/O SUPRAMANIAM BLK 440A CLEMENTI AVENUE 3 #26-10 CLEMENTI CASCADIA SINGAPORE 121440 Contact No Mobile: 81233394	<table> <tr> <td>Cust No/Name</td><td>/SHASI KUMAAR S/O SUPRAMANIAM</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMX3671M / 08/01/202</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416ML5070153</td></tr> <tr> <td>Engine No</td><td>G4FGKH756520</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>ABP AURORA BLACK / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/SHASI KUMAAR S/O SUPRAMANIAM	Reg No/Reg Date	SMX3671M / 08/01/202	Date In/Mileage	/ 0	Chassis No	KNAF3416ML5070153	Engine No	G4FGKH756520	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK
Cust No/Name	/SHASI KUMAAR S/O SUPRAMANIAM														
Reg No/Reg Date	SMX3671M / 08/01/202														
Date In/Mileage	/ 0														
Chassis No	KNAF3416ML5070153														
Engine No	G4FGKH756520														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/03/2022/ 13:17	TLE	261 / Edwin Caina	46956			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3200.00
RENEW FR BUMPER , FR BUMPER BODY KIT , BONNET , FR SUPPORT & LHF FENDER					3 x 640 + 80			2000
E PNT98000								3300.00
RESPRAY FR BUMPER , FR BUMPER BODY KIT , BONNET , LHF FENDER & RHR FENDER (2280
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY								50.00
TOP UP AC GAS								280.00
A 54900099								80.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								80.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								80.00
SUPPLY FR NUMBER PLATE WITH CASING								30
M SUNDRY								80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								40
M SUNDRY								80.00
SUPPLY BODY PNL SEALANT								20
M SUNDRY								50.00
Sundries								
M PANEL ASSY-HOOD					1.00	1502.00	00.00	1502.00
M HINGE ASSY-HOOD,LH					1.00	43.00	00.00	43.00
M HINGE ASSY-HOOD,RH					1.00	43.00	00.00	43.00
M CLIP-HOOD INSULATING PAD MTG					13.00	1.00	00.00	13.00
M PANEL-FENDER,RH					1.00	430.00	00.00	430.00
M COVER-FR BUMPER					1.00	633.00	00.00	633.00
M CAP-FRONT HOOK					1.00	9.00	00.00	9.00
M GRILLE-FRONT BUMPER					1.00	262.00	00.00	262.00
M GRILLE ASSY-RADIATOR					1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE					1.00	38.00	00.00	38.00
M MOULDING-FRONT BUMPER,RH					1.00	36.00	00.00	36.00

Confirm & accepted by

Link Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All repairs are subject to confirmation
- Most parts survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Page 1 of 2



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SHASI KUMAAR S/O SUPRAMANIAM BLK 440A CLEMENTI AVENUE 3 #26-10 CLEMENTI CASCADIA SINGAPORE 121440 Contact No Mobile: 81233394	Cust No/Name /SHASI KUMAAR S/O SUPRAMANIAM Reg No/Reg Date SMX3671M / 08/01/202 Date In/Mileage / 0 Chassis No KNAF3416ML5070153 Engine No G4FGKH756520 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/03/2022/ 13:17	TLE	261 / Edwin Caina	46956			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-SIDE REPEATER, RH	BR			1.00	164.00	00.00	164.00
M	ABSORBER-FRONT BUMPER ENERGY	BR			1.00	84.00	00.00	84.00
M	STIFFNER-FR BPR LWR	nm			1.00	114.00	00.00	114.00
M	AIR DUCT-FR BUMPER, RH	nm			1.00	14.00	00.00	14.00
M	BRACKET-FR BUMPER UPR SIDE MTG	BR			1.00	22.00	00.00	22.00
M	ORNAMENT-KIA NO.115	mc			1.00	32.00	00.00	32.00
M	BEAM COMPLETE-FR BUMPER	DD			1.00	497.00	00.00	497.00
M	CARRIER ASSY-FRONT END MODULE	BR			1.00	675.00	00.00	675.00
M	NEW K3 2020 AURORA BLK PEARL ABP	BR (Body Kit)		1 set	1.00	1721.00	00.00	1721.00

Estimate

SURVEYOR NAME: Steve (LKK) 10/3/22, 1.30pm
 SURVEYOR SIGNATURE: [Signature]
 DATE: 10/3/22
 REMARKS: 7-5 dys

Confirm & accepted by

Nett 13,960.00
 7% GST on 13960.00 977.20
 Total Payable 14,937.20

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.