

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002281/EQY3N2**Date:** 24/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00068522101

Claimant Vehicle No : SNB1247Y **Insured Vehicle No :** YN2650R

Date of Loss: 10/03/2022 Nature of Claim: TP Claim No: SNM22D201701/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB1247Y**

Make & Model: MERCEDES-BENZ S450L, 3.0 4M SEDAN (A) Engine No: 25693030336981

Reg. Date: 30/06/2021 (Man. Year: 2021) Chassis No: W1K2231612A054668

Colour: Grey Odometer: 13686 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45R19 Rear Tyre Size: 255/45R19

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,332.71	3,012.16	2,320.55	43.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	2,840.00	640.00	18.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,812.71	5,852.16	2,960.55	33.59
+ GST 7.00/7.00% (\$\$)	616.89	409.65	207.24	33.59
Nett Amount (\$\$)	9,429.60	6,261.81	3,167.79	33.59

INSPECTION

Date of Assignment: 11/03/2022

Date Inspected: 22/03/2022 Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2022)

Parts: 143 MERCEDES-BENZ S450L 3.0 4M SEDAN (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB1247Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,103.73 FS	*2,103.73 FS
2	1		*REAR BUMPER LOWER	Not Necessary	689.47 FS	*- FS
3	1		*REAR BUMPER CHROME TRIM STRIP	Necessary	252.57 FS	*252.57 FS
4	1		*LEFT REAR BUMPER CHROME TRIM STRIP	Necessary	214.87 FS	*214.87 FS
5	1		*RIGHT REAR BUMPER CHROME TRIM STRIP	Necessary	214.87 FS	*214.87 FS
6	1		*RIGHT REAR BUMPER SIDE CHROME TRIM STRIP	Necessary	113.06 FS	*113.06 FS
7	1		*LEFT REAR BUMPER SIDE CHROME TRIM STRIP	Necessary	113.06 FS	*113.06 FS
8	1		*REAR BUMPER LOWER COVER	Not Necessary	484.47 FS	*- FS
9	1		*REAR CROSSMEMBER	Not Necessary	1,146.61 FS	*- FS
Total Parts (S\$)						5,332.71 3,012.16

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,200.00	960.00
2	RESPRAY REAR BUMPER	New	1,200.00	800.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS,RESET SYSTEM TO STANDARD SETTINGS	New	480.00	480.00
4	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
5	CALIBRATION OF LONG RANGE AND SHORT RANGE RADAR SENSORS	New	480.00	480.00
Gross Labour Cost (\$)			3,480.00	2,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >