



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNB1247Y

Mr Krishnaraj Dayallan

24 Luxus Hill Avenue
Singapore 804886

+6568535787

WIP No

55505

Reg No/Reg Date

SNB1247Y / 30/06/2021

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

W1K2231612A0546685

25693030336981

MB/S 450 4MATIC SEDAN LONG

028 831 Graphite Gr/ 048 804 Sienna Brow

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WCV14459	CRDVCH	10/03/2022/ 16:10	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 7210064782 // 10/03/2022

DRIVE IN/EXCESS : 10/03/2022 // TP VEH NO YN2650R

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET

A BPILAB

CALIBRATION OF LONG RANGE AND SHORT RANGE RADAR SENSORS.

M REAR BUMPER

M REAR BUMPER LOWER

M REAR BUMPER CHROME TRIM STRIP

M LEFT REAR BUMPER CHROME TRIM STRIP

M RIGHT REAR BUMPER CHROME TRIM STRIP

M RIGHT REAR BUMPER SIDE CHROME TRIM STRIP

M LEFT REAR BUMPER SIDE CHROME TRIM STRIP

M REAR BUMPER LOWER COVER

M FRONT CROSSMEMBER

1.00	2103.73	00.00	2103.73
1.00	689.47	00.00	689.47
1.00	252.57	00.00	252.57
1.00	214.87	00.00	214.87
1.00	214.87	00.00	214.87
1.00	113.06	00.00	113.06
1.00	113.06	00.00	113.06
1.00	484.47	00.00	484.47
1.00	1146.61	00.00	1146.61

Raw

Sten (LKK)

22/3/22 3.39p

4 djs

Confirmed & accepted by

W RL

PIN

RL 17

Authorized signatory and company stamp

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

7% GST on **Nett 8,812.71**
812.71

Total Payable 9,429.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg