



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : 7692880192SG

Date: 18th Mar 2022

Our Ref : CC3/AIG22002282/Avce2

M/s Aig Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

Aig Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKA 4680A
ACCIDENT ON 08/03/2022**

Instruction was received to inspect the vehicle Reg. No. SKA 4680A. The inspection was conducted on 10/03/2022 at the premises of M/s Premium Automobiles Pte Ltd, 24 Benoi Sector, Singapore 629857.

The following vehicle information was recorded:

Registration Number	: SKA 4680A
Make/Model	: Audi Q7 2.0 TFSI QU (252 BHP)
Year of Registration	: 2016
Body Colour	: Black
Chassis Number	: WAUZZZ4M2GD028722
Engine Capacity	: 1984 cc
Speedometer Reading	: 65954 km

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$122,785.00 (Sin Dollars: One Hundred Twenty-Two Thousand Seven Hundred Eighty-Five only.) (Include check items S\$25,376.00Nett) (Details see photographs enclosed)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 140,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 76,868.00)

S\$ 63,132.00

Less: Excess

(S\$ 1,000.00)

Nett Liability

S\$ 62,132.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 122,785.00

(Include check items S\$25,376.00Nett)

Less: Excess

(S\$ 1,000.00)

Nett Liability

S\$ 121,785.00

(a) – (b) =

(S\$ 59,653.00)

=====

The amount of estimated saving of S\$59,653.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.