

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0181/2022/JT
DATE : 9-Mar-22
WIP : 15169

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR GOH CHERN HUP
ADDRESS : BLK 142 BUKIT BATOK ST 11
#06-13
SINGAPORE 650142
TELEPHONE : HP +65 94783728
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100455992-05
VEHICLE NO : **SKA 4680 A**
MODEL CODE : AUDI Q7 2.0 TFSI S
MODEL YEAR : 16/3/2016
ENGINE NO : CYR 002367
CHASSIS NO : WAUZZZ4M2GD028722
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Mar-22
PLACE OF ACCIDENT : 109 BUKIT BATOK WEST AVE 6



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKA 4680 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 900.00 500. ✓	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 2,000.00 ✓	
4	TO REMOVE AND CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. RENEW SEAT BELTS, CONTROL UNIT, PILLAR TRIMS AND BOTH CURTAIN AIRBAGS.	S/N \$ 3,600.00 ✓	
5	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES	S/N \$ 2,800.00 ✓	
6	TO RENEW ALTERNATOR, THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$ 980.00 ?	
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$ 2,400.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ <u>13,160.00</u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKA 4680 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF LHS FRONT DOOR.	S/N \$ 280.00	✓
9	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00	✓
10	TO PLACE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	✓
11	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT AND BOTH FRONT CHASSIS FRAME COVER PLATES AND BOTH FRONT CHASSIS FRAME. TO ALIGN BACK BOTH CHASSIS MEMBERS INTO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PART REMOVED	\$ 19,000.00	7200.
12	TO RESPRAY FRONT BUMPER, BOTH FRONT BUMPER LOWER SPOILERS, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT FENDER TOP SUPPORT, BOTH FRONT CHASSIS FRAME WITH COVERS, BOTH UPPER A-PILLARS, LHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 11,000.00	5000 6x600 = 3600 Hinge x 2 = 200 Lower Spoilers x 2 = 150 x 2 = 300 Chassis member x 2 = 500 Wheel Arch x 2 = 400. 5000
13	TO CARRY OUT ALUMINIUM PRIMER WORKS.	S/N \$ 980.00	✓
SUB TOTAL LABOUR CHARGES		\$ 34,460.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKA 4680 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
14	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	✓
15	TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 240.00	✓
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 48,524.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,896.00	✓
2	FRONT BUMPER FIXNG PARTS <i>nee</i>	1	\$ 468.00	✓
3	FRONT BUMPER TOWING EYE <i>Distorted</i>	1	\$ 44.00	✓
4	FRONT BUMPER AIR GUIDE - LH / RH <i>2 Distorted</i>	2	\$ 150.00	✓
5	FRONT BUMPER END CAP - RH	1	\$ 40.00	✓
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>Smashed</i>	1	\$ 309.00	✓
7	FRONT BUMPER GRILLE - LOWER CENTER <i>Distorted</i>	1	\$ 230.00	✓
8	FRONT BUMPER UNDERRUN BAR <i>Distorted</i>	1	\$ 899.00	✓
9	FRONT BUMPER CLOSING ELEMENT - LOWER <i>Distorted</i>	1	\$ 235.00	✓
10	FRONT BUMPER SPOILER - LH / RH <i>Distorted</i>	2	\$ 470.00	✓
11	FRONT BUMPER SPOILER - LH / RH OUTER ?	2	\$ 98.00	?
12	RADIATOR GRILLE <i>Smashed</i>	1	\$ 2,741.00	✓
13	RADIATOR GRILLE COVER <i>Distorted</i>	1	\$ 81.00	✓
14	RADIATOR GRILLE INNER COVER <i>Smashed</i>	1	\$ 69.00	✓
15	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Distorted</i>	2	\$ 664.00	✓
16	FRONT BUMPER END CAP - RH <i>Distorted</i>	1	\$ 38.00	✓
17	SPRING CLIP - LH / RH <i>nee</i>	8	\$ 8.00	✓
18	RADIATOR GRILLE SPOILER - LH / RH INNER <i>Distorted</i>	2	\$ 128.00	✓
19	FRONT BUMPER FOAM FILLER PIECE <i>2 Distorted</i>	1	\$ 192.00	✓
20	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,025.00	✓
SUB TOTAL SPARE PARTS		:	\$ 10,785.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
21	FRONT BUMPER SUPPORT - LH / RH <i>Distorted</i>	2	\$	81.00	✓
22	FRONT BUMPER GUIDE SECTION - LH / RH <i>Distorted</i>	2	\$	100.00	✓
23	FRONT BUMPER TOP COVER <i>Distorted</i>	1	\$	146.00	✓
24	AIR COND STICKER <i>3 New</i>	1	\$	9.00	✓
25	CAUTION STICKER	1	\$	15.00	✓
26	FRONT PARKING AID SNEOR - INNER / OUTER <i>3 Missing</i>	4	\$	976.00 732.	
27	FRONT PARKING AID SENSOR SEAL RING	4	\$	10.00	✓
28	FRONT BUMPER WIRING SET	1	\$	702.00	?
29	HORN - LH / RH <i>RH Band</i>	2	\$	480.00 240	
30	FRONT FENDER - LH / RH <i>Distorted</i>	2	\$	3,638.00	✓
31	FRONT FENDER ATTACHMENT PARTS <i>New</i>	1	\$	79.00	X
32	FRONT FENDER BRACE - LH / RH <i>Bent</i>	2	\$	240.00	✓
33	FRONT FENDER BRACKET - LH / RH <i>Bent</i>	2	\$	144.00	✓
34	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$	74.00	?
35	FRONT FENDER BRACKET END - LH / RH	2	\$	136.00	?
36	FRONT WHEEL HOUSING LINER - LH / RH <i>to n</i>	2	\$	520.00	✓
37	REAR WHEEL HOUSING LINER - LH / RH <i>New</i>	2	\$	520.00	X
38	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>New</i>	1	\$	191.00	X
39	BONNET <i>Distorted</i>	1	\$	7,032.00	✓
40	BONNET ATTACHMENT PARTS <i>New</i>	1	\$	233.00	X
SUB TOTAL SPARE PARTS			:	\$	<u>15,327.00</u>

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET HINGE - LH / RH <i>Best</i>	2	\$ 186.00	✓
42	BONNET HINGE COVER - LH / RH <i>Neu</i>	2	\$ 12.00	✓
43	BONNET ABSORBER <i>Dang d</i>	1	\$ 154.00	✓
44	BONNET IMPACT PROTECTION <i>Ne</i>	1	\$ 119.00	✓
45	BONNET SEAL - LH / RH <i>Neu</i>	2	\$ 136.00	✓
46	HEADLIGHT COVER - LH / RH <i>Delid</i>	2	\$ 228.00	✓
47	FENDER TOP COVER - RH <i>Delid</i>	1	\$ 50.00	✓
48	BONNET STRIKER - LH / RH <i>Best</i>	2	\$ 262.00	✓
49	BONNET BOWDEN CABLE <i>Tam d</i>	1	\$ 64.00	✓
50	BONNET LOCK MICRO-SWITCH <i>Dang d</i>	2	\$ 484.00	✓
51	BONNET LOCK CABLE <i>Dang d</i>	1	\$ 96.00	✓
52	BONNET RELEASE CABLE COVER <i>Dang d</i>	1	\$ 11.00	✓
53	BONNET RELEASE LEVER <i>Dang d</i>	1	\$ 16.00	✓
54	BONNET LOCK CABLE <i>Tam d</i>	1	\$ 125.00	✓
55	BONNET SOUND ABSORBER <i>X4</i>	1	\$ 400.00	✓
56	WATER BOX SOUND ABSORBER - UPPER <i>?</i>	1	\$ 115.00	?
57	HEADLIGHT MOUNTING - LH / RH <i>Smashed</i>	2	\$ 264.00	✓
58	HEADLIGHT - LH / RH <i>RH Smashed, LH culid</i>	2	\$ 21,320.00	✓
59	HEADLIGHT CONTROL UNIT - LH / RH <i>?</i>	2	\$ 1,680.00	?
60	HEADLIGHT FAN <i>?</i>	2	\$ 855.00	?
SUB TOTAL SPARE PARTS		:	\$ 26,577.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	HEADLIGHT POWER MODULE ?	2	\$ 1,680.00 ?	
62	HEADLIGHT HOSE - LH / RH ?	2	\$ 90.00 ?	
63	LIFT CYLINDER - LH / RH <i>Rlt cancelled</i>	2	\$ 434.00 217.	
64	LIFT CYLINDER HOSE ?	1	\$ 113.00 ?	
65	LIFT CYLINDER UPPER HOSE ?	1	\$ 204.00 ?	
66	LIFT CYLINDER PUMP <i>new</i>	1	\$ 171.00 +	
67	WINDSCREEN WASHER SYSTEM PUMP <i>new</i>	1	\$ 137.00 +	
68	WASH WATER RESERVOIR <i>new</i>	1	\$ 240.00 +	
69	WATER FILLER NECK <i>new</i>	1	\$ 65.00 +	
70	LIFT CYLINDER STRAINER <i>new</i>	1	\$ 29.00 +	
71	LIFT CYLINDER END CAP <i>new</i>	1	\$ 24.00 +	
72	LOCK CARRIER <i>Smashed.</i>	1	\$ 1,335.00 ✓	
73	RADIATOR SIDE MEMBER - LH / RH ?	2	\$ 1,068.00 ?	
74	RADIATOR BRACKET - LH / RH	2	\$ 116.00 -	
75	RADIATOR BRACKET LOWER - LH / RH	2	\$ 66.00 -	
76	A/C CONDENSER <i>Dented.</i>	1	\$ 1,022.00 ✓	
77	REFRIGERANT LINE ?	1	\$ 314.00 ?	
78	REFRIGERANT LINE ?	1	\$ 250.00 ?	
79	REFRIGERANT LINE ?	1	\$ 273.00 ?	
80	REFRIGERANT PIPE ?	1	\$ 665.00 ?	
SUB TOTAL SPARE PARTS		:	\$ 8,296.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	OUTSIDE TEMPERATURE SENSOR BRACKET <i>ok</i>	1	\$ 20.00	✓
82	OUTSIDE TEMPERATURE SENSOR <i>missing</i>	1	\$ 64.00	✓
83	AIR TEMPERATURE SENSOR BRACKET <i>ok</i>	1	\$ 5.00	✓
84	CHARGE AIR COOLER <i>Bent</i>	1	\$ 1,150.00	✓
85	PRESSURE HOSE - LH ?	1	\$ 302.00	?
86	PRESSURE HOSE - LOWER ?	1	\$ 233.00	?
87	PRESSURE PIPE ?	1	\$ 315.00	?
88	PRESSURE HOSE - UPPER ?	1	\$ 269.00	?
89	PRESSURE PIPE ?	1	\$ 59.00	?
90	PRESSURE HOSE - RH ?	1	\$ 178.00	?
91	RADIATOR <i>Bent</i>	1	\$ 1,010.00	✓
92	RADIATOR BUSH - RH LOWER ?	2	\$ 20.00	✓
93	RADIATOR BUSH - RH UPPER ?	2	\$ 28.00	✓
94	RADIATOR GROMMET - UPPER ?	2	\$ 22.00	✓
95	RADIATOR SECURING PIN - UPPER ?	2	\$ 6.00	✓
96	RADIATOR COOLANT <i>ok</i>	6	\$ 282.00	✓
97	ADDITIONAL RADIATOR <i>Detected</i>	1	\$ 893.00	✓
98	ADDITIONAL RADIATOR BRACKET <i>Bent</i>	1	\$ 141.00	✓
99	ADDITIONAL RADIATOR BRACKET - LH REAR <i>Bent</i>	1	\$ 30.00	✓
100	RADIATOR AIR GUIDE - LH OUTER ?	1	\$ 52.00	?
SUB TOTAL SPARE PARTS		:	\$ 5,079.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	RADIATOR TWIN FAN RING <i>included</i>	1	\$ 316.00	✓
102	RADIATOR FAN CONTROL UNIT - LH / RH ?	2	\$ 3,232.00	?
103	RADIATOR AIR GUIDE - LH / RH <i>Replaced</i>	2	\$ 66.00	✓
104	RADIATOR AIR GUIDE - UPPER / LOWER <i>Replaced</i>	2	\$ 96.00	✓
105	COOLANT HOSE RELEASE COUPLING - LOWER ?	1	\$ 260.00	?
106	COOLANT HOSE RELEASE COUPLING - UPPER ?	1	\$ 248.00	?
107	COOLANT HOSE <i>storn</i>	1	\$ 123.00	✓
108	CONTROL VALVE ?	1	\$ 391.00	?
109	INTAKE AIR DUCT <i>Replaced</i>	1	\$ 130.00	✓
110	AIR FILTER BOX <i>Replaced</i>	1	\$ 682.00	✓
111	INTAKE HOSE ?	1	\$ 215.00	?
112	INTAKE HOSE ADAPTER ?	1	\$ 34.00	?
113	VACUUM HOSE ?	1	\$ 21.00	?
114	AIR FILTER ELEMENT <i>new</i>	1	\$ 104.00	✓
115	AIR FILTER ELEMENT COVER <i>Replaced</i>	1	\$ 529.00	✓
116	INTAKE MANIFOLD ?	1	\$ 983.00	?
117	THROTTLE VALVE ADAPTER ?	1	\$ 1,126.00	?
118	INTAKE MANIFOLD SUPPORT ?	1	\$ 22.00	?
119	ENGINE MOUNTING - LH / RH ?	2	\$ 826.00	?
120	ENGINE SUPPORT - LH / RH ?	2	\$ 350.00	?
SUB TOTAL SPARE PARTS		:	\$ 9,754.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NGRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	ENGINE SUPPORT BEARING - LH / RH ?	2	\$ 142.00	?
122	FRONT FENDER SIDE MEMEBR - LH Best	1	\$ 1,066.00	✓
123	FRONT FENDER SIDE MEMEBR - RH ?	1	\$ 1,172.00	?
124	CHASSIS CONNECTING PLATE - LH 2nd new	1	\$ 322.00	+
125	CHASSIS CONNECTING PLATE - RH Repair	1	TBC	+
126	CHASSIS CONNECTING PLATE - CENTER ?	2	\$ 190.00	?
127	FRONT WHEEL ARCH COVER - LH / RH Re-d	2	\$ 1,214.00	✓
128	FRONT DOOR COVER - LH xhe on	1	\$ 734.00	+
129	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH 2nd new	2	\$ 842.00	+
130	STEERING WHEEL AIRBAG Activated	1	\$ 3,916.00	✓
131	AIRBAG UNIT	1	\$ 4,969.00	✓
132	HEAD AIRBAG UNIT } Activated	2	\$ 4,280.00	✓
133	AIR BAG CONTROL UNIT	1	\$ 2,848.00	✓
134	AIRBAG CRASH SENSOR	3	TBC	✓
135	FUSE UNIT Activated	1	\$ 613.00	✓
136	SEAT BELT - LH / RH Activated	2	\$ 2,454.00	✓
137	SEAT BELT HEIGHT ADJUSTER - LH / RH new	2	\$ 383.00	+
138	STEERING WHEEL cut	1	\$ 3,142.00	✓
139	DASHBOARD AIR DUCT torn	1	\$ 7,969.00	✓
140	MOULDED HEADLINER crumpled	1	\$ 4,159.00	✓
SUB TOTAL SPARE PARTS		:	\$ 40,415.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 4680 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
141	FRONT GRAB HANDLE - LH / RH ?	2	TBC ?	
142	REAR GRAB HANDLE - LH / RH ?	2	TBC ?	
143	A-PILLAR TRIM - LH / RH ?	2	\$ 872.00 ?	
144	C-PILLAR TRIM - LH / RH ?	2	\$ 524.00 ?	
145	D-PILLAR TRIM - LH / RH ?	2	\$ 1,066.00 ?	
146	NOISE INSULATION ?	1	\$ 723.00 ?	
147	SOUND ABSORBER ?	1	\$ 702.00 ?	
148	STATIC METER ?	1	\$ 12.00 ?	
149	2-PACK EPOXY ADHESIVE <i>new</i>	1	\$ 122.00 ✓	
150	ALUMINIUM POWDER <i>new</i>	1	\$ 637.00 ✓	
151	HARDENER <i>new</i>	1	\$ 232.00 ✓	
152	ALUMINIUM PRIMER <i>new</i>	1	\$ 233.00 ✓	
153	CLEANING BLOCK <i>new</i>	1	\$ 96.00 ✓	
154	STONE CHIP ?	S/N	\$ 180.00 ?	
155	ARYLIC SEALANT <i>new</i>	S/N	\$ 180.00 ✓	
156	CAVITY WAX ?	S/N	\$ 140.00 ✓	
157	FRONT NO PLATE <i>Distorted.</i>	S/N	\$ 60.00 ✓	
158	SUNDRIES ?		\$ 1,000.00 ?	
TOTAL SPARE PARTS		:	\$ 123,012.00	
TOTAL LABOUR CHARGES		:	\$ 48,524.00	
GRAND TOTAL		:	\$ 171,536.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Lij
10/03/22

Not Authorised, 28 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT