

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G

SHF570U

Not Notified
Pruning B&Pain AAD2203-
82738.58

Vehicle No.:
Chassis No.:
Co UEN:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

10 MAR 2022**SHF570U**

JTDKB3FU903092481
200303878K
TOYOTA
PRIUS GEN 4
08/03/2023
SLX7761Y/TOKIO
30/09/2021

- | | PART |
|---|--|
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER |
| 1 | COVER, REAR BUMPER, LOWER |
| 1 | GUARD, REAR BUMPER, CENTER |
| 1 | RETAINER, REAR BUMPER SIDE, LH |
| 1 | RETAINER, REAR BUMPER SIDE, RH |
| 1 | PANEL SUB-ASSY, BACK DOOR |
| 1 | PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2 |
| 1 | PLATE, BACK DOOR NAME, NO.1 |
| 1 | ORNAMENT SUB-ASSY, BACK DOOR |
| 1 | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE |
| 1 | BOARD ASSY, BACK DOOR TRIM |
| 1 | WEATHERSTRIP, BACK DOOR |
| 1 | COVER, DECK TRIM, REAR |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK |
| 1 | STAY ASSY, BACK DOOR, LH |
| 1 | STAY ASSY, BACK DOOR, RH |
| 1 | HINGE ASSY, BACK DOOR, LH |
| 1 | HINGE ASSY, BACK DOOR, RH |

LIST

\$	<i>By</i> 332.70	<i>2</i> ✓
\$	<i>Ad</i> 22.00	✓
\$	<i>Ad</i> 374.50	✓
\$	<i>Sm</i> 132.60	X
\$	<i>Dir</i> 132.60	✓
\$	<i>K</i> 1,147.80	X
\$	<i>Sm</i> 54.60	—
\$	<i>Sm</i> 54.60	—
\$	<i>Sm</i> 47.90	—
\$	<i>mgcm</i> 913.60	✓
\$	<i>Sm</i> 259.20	X
\$	<i>Sm</i> 372.30	X
\$	<i>Sm</i> 126.70	X
\$	<i>K</i> 651.00	X
\$	<i>Sm</i> 242.50	X
\$	<i>Sm</i> 242.50	X
\$	<i>K</i> 61.00	X
\$	<i>K</i> 61.00	X

TOTAL	\$	5,229.10
25%	\$	1,307.28
	\$	3,921.83

Special Nett

- | | |
|---|----------------------|
| 1 | SET PARKING AID |
| 1 | SET REAR BUMPER CLIP |
| 2 | WINDSCREEN SEALANT |
| 1 | WINDSCREEN MOULDING |

\$	<i>Sm</i> 700.00	X
\$	<i>Sm</i> 95.00	<i>600.00</i>
\$	<i>Sm</i> 150.00	X
\$	<i>Sm</i> 200.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2203-

SHF570U

1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	305n
1 REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	305n
1 REAR BUMPER PROTECTOR	\$	n/p	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	X
1 END PANEL TRIM CLIP	\$	na	65.00	X
1SET BUMPER CLIP FRT	\$	na	95.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	na	200.00	X
TOTAL	\$		2,060.00	

TOTAL PARTS \$ 5,981.83**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	na	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	3001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	4	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	4	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	4	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U

AAD2203-

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Towing Fees	\$	nn	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	4401
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	151
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	220.00	X
To replace, refix and top up coolant for radiator	\$	nn	170.00	X
To lift-up / out engine with gear box and refit.	\$	nn	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	nn	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn	380.00	X
TOTAL	\$		10,290.00	

Over All Total \$ 16,271.83

16,636.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

25 DAYS

2 1/2 days

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U

AAD2203-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY

SHF570U

JTDKB3FU903092481

200303878K

TOYOTA

PRIUS **GEN 4**

08/03/2023

SLX7761Y/TOKIO

30/09/2021

1 COVER, REAR BUMPER

PART

		LIST	
	\$	<i>Bu</i>	485.60 ✓
TOTAL	\$		485.60
25%	\$		121.40
	\$		364.20