

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U

Not Withheld
Penny B & Paim AAD2203-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 MAR 2022**SHF570U**

JTDKB3FU903092481

200303878K

TOYOTA

PRIUS GEN 4

08/03/2023

SLX7761Y/TOKIO

30/09/2021

	PART
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	RETAINER, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, RH
1	PANEL SUB-ASSY, BACK DOOR
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	BOARD ASSY, BACK DOOR TRIM
1	WEATHERSTRIP, BACK DOOR
1	COVER, DECK TRIM, REAR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH

	LIST
\$	<i>RM</i> 332.70 ✓
\$	<i>RM</i> 22.00 ✓
\$	<i>RM</i> 374.50 ✓
\$	<i>RM</i> 132.60 X
\$	<i>RM</i> 132.60 ✓
\$	<i>RM</i> 1,147.80 X
\$	<i>RM</i> 54.60 —
\$	<i>RM</i> 54.60 —
\$	<i>RM</i> 47.90 —
\$	<i>RM</i> 913.60 ✓
\$	<i>RM</i> 259.20 X
\$	<i>RM</i> 372.30 X
\$	<i>RM</i> 126.70 X
\$	<i>RM</i> 651.00 X
\$	<i>RM</i> 242.50 X
\$	<i>RM</i> 242.50 X
\$	<i>RM</i> 61.00 X
\$	<i>RM</i> 61.00 X
TOTAL	\$ 5,229.10
25%	\$ 1,307.28
	\$ 3,921.83

Special Nett

1SET PARKING AID	\$	<i>RM</i> 700.00 X
1SET REAR BUMPER CLIP	\$	<i>RM</i> 95.00 <i>60/100</i>
2 WINDSCREEN SEALANT	\$	<i>RM</i> 150.00 X
1 WINDSCREEN MOULDING	\$	<i>RM</i> 200.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2203-

SHF570U

1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	305N
1 REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	305N
1 REAR BUMPER PROTECTOR	\$	na	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	X
1 END PANEL TRIM CLIP	\$	na	65.00	X
1SET BUMPER CLIP FRT	\$	na	95.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	na	200.00	X
TOTAL	\$		2,060.00	

TOTAL PARTS \$ 5,981.83**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$	na	300.00	X
----	----	--------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	na	380.00	X
----	----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		2,200.00	3001
----	--	----------	------

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	na	380.00	X
----	----	--------	---

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$	4	180.00	X
----	---	--------	---

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$	4	480.00	X
----	---	--------	---

To transfer of Fender fittings, attachments and perform water seepage test.

\$	4	480.00	X
----	---	--------	---

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$	4	380.00	X
----	---	--------	---

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U**AAD2203-**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na	250.00	X
Towing Fees	\$	na	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	4401
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	151
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	220.00	X
To replace, refix and top up coolant for radiator	\$	na	170.00	X
To lift-up / out engine with gear box and refit.	\$	na	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	na	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	na	380.00	X
TOTAL	\$		10,290.00	

Over All Total \$ 16,271.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(PART-BY-PART) Repair Days**25 DAYS**
2 1/2 days

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U**AAD2203-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY**SHF570U**

JTDKB3FU903092481

200303878K

TOYOTA

PRIUS GEN 4

08/03/2023

SLX7761Y/TOKIO

30/09/2021

1 COVER, REAR BUMPER

PART

		LIST	
	\$	<i>Bu</i>	485.60 ✓
TOTAL	\$		485.60
25%	\$		121.40
	\$		364.20