

ASS. REC. BY:

REF:

7M1/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

R 77,858

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SIF 5704

Yr Regn:

09, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c.

1788

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

36899

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J7DK B3F4 903 092481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

195/65R15

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

8/3/22

D.O.I.

10/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U*Not Authorised*
Penny Bepain AAD2203-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 MAR 2022**SHF570U**

JTDKB3FU903092481

200303878K

TOYOTA

PRIUS GEN 4

08/03/2023

SLX7761Y/TOKIO

30/09/2021

	PART		LIST	
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>RM</i> 332.70	<i>Z</i> ✓
1	COVER, REAR BUMPER, LOWER	\$	<i>RM</i> 22.00	✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>RM</i> 374.50	✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>RM</i> 132.60	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>RM</i> 132.60	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>RM</i> 1,147.80	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>RM</i> 54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>RM</i> 54.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>RM</i> 47.90	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>RM</i> 913.60	✓
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>RM</i> 259.20	X
1	WEATHERSTRIP, BACK DOOR	\$	<i>RM</i> 372.30	X
1	COVER, DECK TRIM, REAR	\$	<i>RM</i> 126.70	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>RM</i> 651.00	X
1	STAY ASSY, BACK DOOR, LH	\$	<i>RM</i> 242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	<i>RM</i> 242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>RM</i> 61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>RM</i> 61.00	X
TOTAL		\$	5,229.10	
25%		\$	1,307.28	
		\$	3,921.83	

Special Nett

1SET PARKING AID	\$	<i>RM</i> 700.00	X
1SET REAR BUMPER CLIP	\$	<i>RM</i> 95.00	<i>60/100</i>
2 WINDSCREEN SEALANT	\$	<i>RM</i> 150.00	X
1 WINDSCREEN MOULDING	\$	<i>RM</i> 200.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2203-

SHF570U

1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	nn	80.00	30sn
1 REAR TAILGATE STICKER "6555-3333"	\$	nn	80.00	30sn
1 REAR BUMPER PROTECTOR	\$	nsp	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	nn	85.00	X
1 END PANEL TRIM CLIP	\$	nn	65.00	X
1SET BUMPER CLIP FRT	\$	nn	95.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	nn	200.00	X
TOTAL	\$		2,060.00	

TOTAL PARTS \$ 5,981.83**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 3001

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 4 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ 4 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 4 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 4 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U**AAD2203-**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Towing Fees	\$	nn	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	4401
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	151
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	220.00	X
To replace, refix and top up coolant for radiator	\$	nn	170.00	X
To lift-up / out engine with gear box and refit.	\$	nn	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	nn	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn	380.00	X
TOTAL	\$		10,290.00	

Over All Total \$ 16,271.83**(PART-BY-PART) Repair Days****25 DAYS****2 1/2 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF570U**AAD2203-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY**SHF570U**

JTDKB3FU903092481

200303878K

TOYOTA

PRIUS GEN 4

08/03/2023

SLX7761Y/TOKIO

30/09/2021

PART

1 COVER, REAR BUMPER

		LIST	
	\$	<i>Mr</i>	485.60 ✓
TOTAL	\$		485.60
25%	\$		121.40
	\$		364.20

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHF570U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Mar 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H11593
Chassis No.:	JTDKB3FU903092481
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	30 Sep 2021
First Registration Date:	30 Sep 2021
Transfer Count:	0
Actual ARF Paid:	\$7,030.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2029
PARF Rebate Amount:	\$5,272.00

Intended COE Rebate Details

COE Expiry Date:	29 Sep 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,364.00
COE Rebate Amount:	\$29,891.00
Total Rebate Amount:	\$35,163.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Mar 2022

OK