

ASS. REQ. BY:

REF:

C72/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 878,702/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S14D 28E Yr Regn: 10 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1798Colour M.P. White / R A/C: Insured / Std / NI / NASp. Reading — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 77DKB3FU X 0309 2537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Poilun

Front

Rear

R/Bal. 3 mmR/Bal. 6 mmL/Bal. 3 mmL/Bal. 6 mmD.O.A. 27/12/22D.O.I. 10/3/2022

Survey held at _____

Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA not ready, set B1. Nothing flt

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

Survey Fee: _____

Transportation: _____

☐ : Interview (\$

) : Fines

☐ : Tech Invs (\$

) : Others

☐ : Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Authenik

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD28E

AAD2202-119

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 MAR 2022

SHD28E

JTDKB3FUX03092537

200303878K

TOYOTA

PRIUS GEN 4

27/02/2022

SGT7253C/CHINA

29/10/2021

PART		LIST	
1	COVER, FRONT BUMPER	\$	521.00 ✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	110.50 ✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	716.60 ✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	246.10 ✓
1	ABSORBER, FRONT BUMPER, LOWER	\$	132.70 ✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	80.20 ✓
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	80.10 ✓
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	82.30 ✓
1	COVER, ENGINE UNDER, NO.1	\$	472.40 ?
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	241.90 ?
1	EXTENSION, FRONT BUMPER, RH	\$	120.10 ?
1	EXTENSION, FRONT BUMPER, LH	\$	120.10 ✓
1	MOULDING, FRONT BUMPER SIDE, LH	\$	95.60 X
1	MOULDING, FRONT BUMPER SIDE, RH	\$	95.60 ✓
1	COVER, FRONT BUMPER HOLE, LH	\$	30.20 ✓
1	COVER, FRONT BUMPER HOLE, RH	\$	30.20 X
1	LAMP ASSY, FOG, LH	\$	237.10 ✓
1	LAMP ASSY, FOG, RH	\$	237.10 X
1	UNIT ASSY, HEADLAMP, LH	\$	2,637.60 ✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	3,772.50 ✓
1	UNIT ASSY, HEADLAMP, RH	\$	2,637.60 ✓
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	3,772.50 ?
1	GRILLE SUB-ASSY, RADIATOR	\$	422.50 ✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	178.60 ✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	105.80 ✓
1	SUPPORT, RADIATOR, UPPER RH	\$	78.90 ✓
1	SUPPORT, RADIATOR, UPPER LH	\$	78.90 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2202-119**SHD28E**

1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$	<i>B</i>	377.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	<i>R</i>	409.90	✓
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	<i>Bu</i>	245.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	<i>R</i>	245.10	X
1	COVER SUB-ASSY, QUARTER PILLAR, LH	\$	<i>R</i>	207.30	✓
1	HOOD SUB-ASSY	\$	<i>R</i>	983.10	✓
1	HINGE ASSY, HOOD, LH	\$	<i>B</i>	58.90	✓
1	HINGE ASSY, HOOD, RH	\$	<i>O/Y</i>	58.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	<i>R</i>	78.30	✓
1	INSULATOR, HOOD	\$	<i>Refum</i>	410.90	✓
1	LOCK ASSY, HOOD	\$	<i>R</i>	135.00	✓
1	SEAL, HOOD TO FRONT END PANEL	\$	<i>R</i>	85.50	✓
1	COVER SUB-ASSY, ENGINE, NO.1	\$		313.00	?
1	WIRE, ENGINE ROOM MAIN	\$		7,323.90	?
1	HORN ASSY, HIGH PITCHED	\$		134.80	?
1	HORN ASSY, LOW PITCHED	\$		134.80	?
1	GUIDE, RADIATOR AIR, NO.1 LH	\$		69.90	?
1	GUIDE, RADIATOR AIR, NO.1 RH	\$		65.30	?
1	GUIDE, RADIATOR AIR, NO.3	\$		112.70	?
1	GUIDE, RADIATOR AIR, NO.2	\$		53.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$		32.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.2	\$		32.60	?
1	INLET, AIR CLEANER, NO.1	\$	<i>Ref</i>	155.60	✓
1	INLET, AIR CLEANER, NO.3	\$	<i>Ref</i>	42.10	✓
1	INLET, AIR CLEANER, NO.2	\$		112.70	?
1	HOSE, AIR CLEANER, NO.1	\$		74.00	?
1	JAR ASSY, WINDSHIELD WASHER	\$		219.10	?
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	<i>P</i>	292.40	X
1	INLET SUB-ASSY, WASHER	\$	<i>P</i>	67.00	X
1	CONDENSER ASSY, COOLER	\$	<i>R</i>	1,783.20	✓
1	HOSE SUB-ASSY, SUCTION	\$		646.80	?
1	HOSE SUB-ASSY, DISCHARGE	\$		402.90	?
1	PIPE SUB-ASSY, SUCTION	\$		465.80	?
1	SENSOR, AIRCONDITIONER PRESSURE	\$		342.80	?
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$		691.00	?
1	COMPRESSOR ASSY, W/MOTOR	\$		4,771.60	?
1	RADIATOR ASSY	\$	<i>R</i>	2,218.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2202-119**SHD28E**

1 SHROUD, FAN	\$	264.70	✓
1 FAN, RH	\$	281.30	✓
1 FAN, LH	\$	219.10	✓
1 MOTOR, COOLING FAN, LH	\$	655.10	✓
1 MOTOR, COOLING FAN, RH	\$	535.50	✓
1 TANK ASSY, INVERTER RESERVE	\$	443.00	✓
1 INVERTER WATER PUMP ASSY(W/MOTOR)	\$	518.60	✓
1 BATTERY	\$	<i>Per</i> 1,584.90	✓
1 CLAMP, BATTERY, NO.2	\$	<i>n</i> 51.80	X
1 CLAMP SUB-ASSY, BATTERY	\$	115.50	✓
1 TERMINAL, BATTERY POSITIVE	\$	<i>Per</i> 58.10	X
1 COVER, FUSIBLE LINK	\$	<i>Per</i> 33.90	X
1 SENSOR ASSY, BATTERY STATE	\$	306.10	✓
1 BLOCK ASSY, FUSIBLE LINK	\$	119.60	✓
1 TANK, RESERVE SEALED W/O CAP	\$	151.40	✓
1 CLEANER ASSY, AIR	\$	<i>CM</i> 1,147.00	✓
1 BRACKET, HEADLAMP, LH	\$	<i>CM</i> 34.80	✓
1 BRACKET, HEADLAMP, RH	\$	34.80	✓
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$	<i>Dir</i> 47.50	✓
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$	<i>n</i> 47.50	X
1 BRACKET, FRONT BUMPER SIDE, LH	\$	59.30	✓
1 BRACKET, FRONT BUMPER SIDE, RH	\$	59.30	✓
1 BRACKET, RADIATOR GRILLE MOUNTING, LH	\$	36.60	✓
1 BRACKET, RADIATOR GRILLE MOUNTING, RH	\$	36.60	✓
1 MEMBER SUB-ASSY, FRONT SIDE, RH	\$	<i>n</i> 2,342.30	X
1 MEMBER SUB-ASSY, FRONT SIDE, LH	\$	<i>n</i> 2,342.30	X
1 COVER, RADIATOR SUPPORT OPENING	\$	<i>Per</i> 211.50	X
1 ACTUATOR ASSY, SHIFT CONTROL	\$	1,036.40	✓
1 COOLER, MOTOR COOLING	\$	297.20	✓
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$	<i>Per</i> 1,436.60	X
1 COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	<i>any</i> 100.40	✓
1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>Per</i> 100.40	X
1 FENDER SUB-ASSY, FRONT RH	\$	<i>n</i> 977.80	X
1 LINER, FRONT FENDER, RH	\$	<i>Per</i> 202.50	X
1 EMBLEM, SIDE PANEL, RH	\$	<i>n</i> 54.60	X
1 FENDER SUB-ASSY, FRONT LH	\$	<i>Per</i> 977.80	✓
1 LINER, FRONT FENDER, LH	\$	<i>Dir</i> 210.30	✓

Trans-cab Auto Services Pte Ltd

AAD2202-119

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD28E

- 1 EMBLEM, SIDE PANEL
- 1 AIR BAG ASSY, CURTAIN SHIELD, LH
- 1 AIR BAG ASSY, CURTAIN SHIELD, RH
- 1 COMPUTER ASSY, AIR BAG
- 1 SENSOR, AIR BAG, FRONT LH
- 1 SENSOR, AIR BAG, FRONT RH
- 1 HEADLINING ASSY, ROOF
- 1 AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR
- 1 AIR BAG ASSY, INSTRUMENT PANEL, LOWER NO.1
- 1 WHEEL ASSY, STEERING
- 1 BELT ASSY, FRONT SEAT OUTER, RH
- 1 BELT ASSY, FRONT SEAT OUTER, LH
- 1 BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH
- 1 BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH
- 1 FR LH SEAT

	\$	<i>na</i> 54.60	✓
	\$	<i>Burn</i> 1,748.10	✓
	\$	<i>na</i> 1,748.10	✓
	\$	<i>na</i> 1,546.00	✓
	\$	<i>na</i> 373.90	✓
	\$	<i>na</i> 373.90	✓
	\$	<i>na</i> 2,125.70	✓
	\$	<i>Burn</i> 3,869.30	✓
	\$	<i>na</i> 1,907.00	✓
	\$	1,492.50	✓
	\$	<i>na</i> 995.10	✓
	\$	<i>na</i> 995.10	✓
	\$	<i>na</i> 995.10	✓
	\$	<i>na</i> 995.10	✓
	\$	<i>BT/na</i> TBA <i>Ignore</i>	✓
TOTAL	\$	77,539.20	
25%	\$	19,384.80	
	\$	58,154.40	

Special Nett

- 1SET BUMPER CLIP FRT
- 1 FRONT NUMBER PLATE WITH MOULDING
- 1SET CLIP, FRONT FENDER LINER
- 2 FENDER CLIP
- 1SET FRNT BUMPER RETAINER CLIP
- 4L Radiator Coolant
- 1 HOOD INSULATOR CLIP
- 1 Engine Under Cover Clip
- 2 DOOR STICKER 'TRANSCAB'

	\$	<i>na</i> 95.00	<i>605m</i>
	\$	<i>na</i> 200.00	<i>45m</i>
	\$	<i>na</i> 85.00	X
	\$	<i>n/s na</i> 130.00	<i>LT</i>
	\$	<i>na</i> 85.00	X
	\$	<i>na</i> 120.00	<i>405m</i>
	\$	<i>na</i> 55.00	✓
	\$	<i>na</i> 60.00	X
	\$	<i>na</i> 200.00	X
TOTAL	\$	1,030.00	

TOTAL PARTS \$ 59,184.40**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ *na* 300.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2202-119**SHD28E**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 1201

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 9001

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ nn 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ nn 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 380.00 1001

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 901

Towing Fees

\$ (Bill) 150.00 1201

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 13201

To Check Electrical Lighting Concerned.

\$ 170.00 201

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 220.00 X

To replace, refix and top up coolant for radiator

\$ 170.00 501

Trans-cab Auto Services Pte Ltd

AAD2202-119

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD28E

To lift-up / out engine with gear box and refit. \$ 22 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair. \$ 380.00 A

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators. \$ 380.00 200

TOTAL \$ 9,560.00

Over All Total \$ 68,744.40

(PART-BY-PART) Repair Days

25 DAYS
16 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD28E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Mar 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H12669
Chassis No.:	JTDKB3FUX03092537
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	29 Oct 2021
First Registration Date:	29 Oct 2021
Transfer Count:	0
Actual ARF Paid:	\$7,030.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Oct 2029
PARF Rebate Amount:	\$5,272.00

Intended COE Rebate Details

COE Expiry Date:	28 Oct 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,186.00
COE Rebate Amount:	\$29,748.00
Total Rebate Amount:	\$35,020.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Mar 2022

OK