



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMG522U

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 55390
Reg No/Reg Date SMG522U / 20/12/2018
Date In/Mileage 39509
Chassis No WDD2130422A5758219
Engine No 27492031693079
Make/Model MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE
Colour/Trim 029 992 Selenite Gr/ 048 814 Nappa Nut 8

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	01/12/2022/ 18:16	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPN SUN
POLICY NO/ACC DATE : 5120085604-01 // 4-3-2022
DRIVE IN/TP VEH NUMBER : 4-3-2022 // GBJ7376T - CHINA TAIPING
DATE IN/DATE SURVEY:
DIRECT SETTLEMENT BY:

- A BPILAB
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.
- A BPIRES
RESPRAY REAR BUMPER & RH/REAR FENDER
- A BPILAB
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT
- A BPILAB
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT
- M LH/REAR BUMPER CHROME MOULDING 1.00 152.14 00.00 152.14
- M RH/REAR BUMPER CHROME MOULDING 1.00 152.14 00.00 152.14
- M REAR LOWER BLACK TRIM BUMPER 1.00 336.57 00.00 336.57
- M REAR BUMPER LOWER CHROME MOULDING 1.00 362.74 00.00 362.74
- M LH/TAIL PIPE BRACKET 1.00 71.09 00.00 71.09
- M RIVET 12.00 4.93 00.00 59.16
- M DISTANCE SENSOR 1.00 195.43 00.00 195.43
- R REAR BUMPER 1.00 1565.55 00.00 1565.55

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Nett 6,634.82
7% GST on 6634.82 464.44
Total Payable 7,099.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg