



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22002297/Eqy3e2	
			Date: 09/05/2022	
			Code: UOI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	Insured Veh.		Veh. Inspected	SKW 6366D
	Policy No.	DH0M110164721800	Coverage (\$)	0.00
	Claim No.	M11D14872203	Excess (\$)	800.00
	Assign From	Josephine Wong	Assign Date	11/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ C180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD2050402R113918	Colour	BLUE
	Odometer	68407 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	PIRELLI	5 mm
	L/H Front Tyre	225/50 R17	PIRELLI	5 mm
	R/H Rear Tyre	225/50 R17	PIRELLI	5 mm
	L/H Rear Tyre	225/50 R17	PIRELLI	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	10/03/2022	Inspection Date	14/03/2022
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$83,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	