



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

Finalization

## ESTIMATE FOR SKW6366D

Chua Bok Hee

c/o United Overseas Insurance Lt  
Motor Claims Department  
146 Robinson Road #02-01 UOI Bld  
Singapore 068909

\*Mobile: +6594767188

### Vehicle & Document Information

WIP No **55497**  
Reg No/Reg Date **SKW6366D / 09/11/2015**  
Date In/Mileage **15/03/2022/ 68407**  
Chassis No **WDD2050402R113918**  
Engine No **27491030463271**  
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**  
Colour/Trim **028 890 Cavansit Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSI00003	Cash	11/04/2022/ 18:15		371 / Go Chee Han					
Z REQUEST					Customer Request				
M BPNSUN					POLICY NO/ACC DATE : DHOM110164721800 // 10-3-2022				
					TOW IN/EXCESS : 10-3-2022 // \$800				
					DATE IN/DATE SURVEY: 14-3-2022 // STEVE - LKK				
					BY/AUTHORIZED ON : 15-3-2022 // SHIAU CHAN - LKK				
A BPILAB					DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960.00
A BPIRES					RESpray RH/FRONT FENDER			0.05	800.00
A BPILAB					USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB					TO REMOVE/REPLACE RH/FRONT AFFECTED SUSPENSION WITH ENGINE CARRIER.				1920.00
A BPILAB					ATTACH/DETACH ENGINE SUPPORT FIXTURE FOR NECESSARY REPAIRS.NETT				480.00
A BPILAB					TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
S BPNSUB					TRANSFER 01 PC TYRE FROM RIM				60.00
A 97250001					CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM				180.00
A 97510101					BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS				120.00
A BPILAB					TO REMOVE,REPLACE HEADLAMP WITH FOCUS . NETT				120.00
M BPNSUN					TOWING FEE				120.00
X BPNEXC					INSURANCE EXCESS				-800.00
X STEERING GEAR						1.00	7544.01	00.00	7544.01

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## Finalization

## ESTIMATE FOR SKW6366D

Chua Bok Hee

c/o United Overseas Insurance Lt  
Motor Claims Department  
146 Robinson Road #02-01 UOI Bld  
Singapore 068909  
\*Mobile: +6594767188

### Vehicle & Document Information

WIP No **55497**  
Reg No/Reg Date **SKW6366D / 09/11/2015**  
Date In/Mileage **15/03/2022/ 68407**  
Chassis No **WDD2050402R113918**  
Engine No **27491030463271**  
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**  
Colour/Trim **028 890 Cavansit B1/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00003	Cash	11/04/2022/ 18:15		371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X INTEGRAL CARRIER	1.00	2497.57	00.00	2497.57
X RIGHT CONTROL ARM	1.00	844.91	00.00	844.91
X RH/FRONT STEERING KNUCKLE	1.00	1410.99	00.00	1410.99
X FRT WHEEL BEARING	1.00	562.47	00.00	562.47
X RH/FRONT STRUT ROD	1.00	634.59	00.00	634.59
X SPRING LINK	1.00	631.45	00.00	631.45
X NUT W FLANGE, BINDING	1.00	9.80	00.00	9.80
X NUT-A-WASHER ASSEMBLY	2.00	15.68	00.00	31.36
X RH/FRONT DISK WHEEL	1.00	641.32	00.00	641.32
X RH/FRONT FENDER	1.00	955.58	00.00	955.58
X SEAM SEAL	1.00	64.24	00.00	64.24
X RH/FRONT SHOCK-ABSORBER STRUT	1.00	756.11	00.00	756.11
X HEXAGON HEAD BOLT	1.00	17.69	00.00	17.69
X THREAD ROLLING SCREW	2.00	8.80	00.00	17.60
X SCREW	2.00	33.64	00.00	67.28
X SCREW W RND. HEXAL. HEAD	2.00	16.87	00.00	33.74
X SCREW W RND. HEXAL. HEAD	2.00	23.31	00.00	46.62

Confirmed & accepted by

Nett **21,647.33**  
7% GST on **21647.33** **1515.31**

Authorized signatory and company stamp

Total Payable **23,162.64**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKW6366D

Chua Bok Hee

c/o United Overseas Insurance Lt  
Motor Claims Department  
146 Robinson Road #02-01 UOI Bld  
Singapore 068909

\*Mobile: +6594767188

## Vehicle &amp; Document Information

WIP No **55497**  
Reg No/Reg Date **SKW6366D / 09/11/2015**  
Date In/Mileage **15/03/2022/ 68407**  
Chassis No **WDD2050402R113918**  
Engine No **27491030463271**  
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**  
Colour/Trim **028 890 Cavansit Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00003	Cash	11/04/2022/ 18:14	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : DHOM10164721800 // 10-3-2022

TOW IN/EXCESS : 10-3-2022 // \$800

DATE IN/DATE SURVEY: 14-3-2022 // STEVE - LKK

BY/AUTHORIZED ON : 15-3-2022 // SHIAU CHAN - LKK

X HEXAGON HEAD BOLT  
X THREAD ROLLING SCREW  
X SCREW  
X SCREW W RND. HEXAL. HEAD  
X SCREW W RND. HEXAL. HEAD

1.00 17.69 00.00  
2.00 8.80 00.00  
2.00 33.64 00.00  
2.00 16.87 00.00  
2.00 23.31 00.00

17.69  
17.60  
67.28  
33.74  
46.62

Confirmed &amp; accepted by

7% GST on **Nett 182.93**  
**182.93 12.81**

Authorized signatory and company stamp

**Total Payable 195.74**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg