



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKW6366D

Chua Bok Hee

Blk 102 Teck Whye Lane
#04-420
Singapore 680102

Mobile: +6594767188

Vehicle & Document Information

WIP No 55497
Reg No/Reg Date SKW6366D / 09/11/2015
Date In/Mileage / 0
Chassis No WDD2050402R113918
Engine No 27491030463271
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 028 890 Cavansit B1/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
CSI00003	Cash	10/03/2022/ 18:23	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DHOM110164721800 // 10-3-2022								
TOW IN/EXCESS : 10-3-2022 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESPRAY RH/FRONT FENDER								
					0.10			380.00 /
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
A BPILAB								
TO REMOVE/REPLACE RH/FRONT AFFECTED SUSPENSION WITH ENGINE CARRIER.								
A BPILAB								
ATTACH/DETACH ENGINE SUPPORT FIXTURE FOR NECESSARY REPAIRS.NETT								
A BPILAB								
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								
S BPNSUB								
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM,(RUN FLAT)								
WHEEL BALANCE AND INSTALL NEW VALVE HEAD								
A 97250001								
CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM								
A 97510101								
BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS								
A BPILAB								
TO REMOVE,REPLACE HEADLAMP WITH FOCUS . NETT								
M BPNSUN								
TOWING FEE					1.00	7544.01	00.00	7544.01 /
M STEERING GEAR					2.00	14.64	00.00	29.28
M COMBINATION NUT								

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKW6366D

Chua Bok Hee

Blk 102 Teck Whye Lane
#04-420
Singapore 680102

Mobile: +6594767188

Vehicle & Document Information

WIP No 55497
Reg No/Reg Date SKW6366D / 09/11/2015
Date In/Mileage / 0
Chassis No WDD2050402R113918
Engine No 27491030463271
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 028 890 Cavansit B1/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00003	Cash	10/03/2022/ 18:23	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M MOUNTING PLATE	1.00	16.93	00.00	16.93
M INTEGRAL CARRIER	1.00	2497.57	00.00	2497.57
M RH/FRONT SHOCK-ABSORBER STRUT	1.00	756.11	00.00	756.11
M RH/FRONT UPPER CONTROL ARM	1.00	844.91	00.00	844.91
M RH/FRONT STEERING KNUCKLE	1.00	1410.99	00.00	1410.99
M RH/FRONT WHEEL BEARING	1.00	562.47	00.00	562.47
M RH/FRONT STRUT ROD	1.00	634.59	00.00	634.59
M RH/FRONT SPRING LINK	1.00	631.45	00.00	631.45
M NUT W FLANGE, BINDING	1.00	9.80	00.00	9.80
M NUT-A-WASHER ASSEMBLY	2.00	15.68	00.00	31.36
M RH/FRONT DISK WHEEL	1.00	641.32	00.00	641.32
M RH/FRONT FENDER	1.00	955.58	00.00	955.58
M SEAM SEAL	1.00	64.24	00.00	64.24
M RH/HEADLAMP UNIT	1.00	3366.07	00.00	3366.07

ESTIMATE

Steve (LKK)
14/3/22, 11.00am

OD-MAL
Exc rr-?
6 dy
P/P
L/R

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirmed & accepted by

- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on **Nett 26,796.68**
1875.77

Total Payable 28,672.45

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg