



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKW6366D

Chua Bok Hee

c/o United Overseas Insurance Lt
Motor Claims Department
146 Robinson Road #02-01 UOI Bld
Singapore 068909

*Mobile: +6594767188

Vehicle & Document Information

WIP No 55497
Reg No/Reg Date SKW6366D / 09/11/2015
Date In/Mileage 15/03/2022/ 68407
Chassis No WDD2050402R113918
Engine No 27491030463271
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 028 890 Cavansit Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00003	Cash	11/04/2022/ 18:14	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : DHOM10164721800 // 10-3-2022

TOW IN/EXCESS : 10-3-2022 // \$800

DATE IN/DATE SURVEY: 14-3-2022 // STEVE - LKK

BY/AUTHORIZED ON : 15-3-2022 // SHIAU CHAN - LKK

X HEXAGON HEAD BOLT
X THREAD ROLLING SCREW
X SCREW
X SCREW W RND. HEXAL. HEAD
X SCREW W RND. HEXAL. HEAD

1.00 17.69 00.00
2.00 8.80 00.00
2.00 33.64 00.00
2.00 16.87 00.00
2.00 23.31 00.00

17.69
17.60
67.28
33.74
46.62

Confirmed & accepted by

7% GST on **Nett 182.93**
182.93 12.81

Authorized signatory and company stamp

Total Payable 195.74

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg