



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TAN JUN HONG			Ref: CS/ASM21013161/Kty3e2 Date: 14/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1575R	Veh. Inspected	SJL 8442Z
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03PE2	Excess (\$)	0.00
	Assign From	TAN JUN HONG	Assign Date	27/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALLION 1.5 A	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	NZT2603030153	Colour	WHITE
	Odometer	210955 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/70 R14	FALKEN	9 mm
	L/H Front Tyre	185/70 R14	FALKEN	9 mm
	R/H Rear Tyre	185/70 R14	FALKEN	9 mm
	L/H Rear Tyre	185/70 R14	FALKEN	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/12/2021	Inspection Date	28/12/2021
	Survey held at	RS AUTO SERVICES 160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	