



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 1919M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	2,985.60	-
1	REAR BUMPER SIDE RETAINER PLATE (LH)	NOT NECESSARY	110.80	-
1	REAR BUMPER SIDE BRACKET PLATE (LH)	NOT NECESSARY	98.70	-
1	REAR BUMPER LOWER	GRAZED / DEFORMED	1,452.00	1,120.00
1	REAR BUMPER LAMP (LH)	NOT NECESSARY	819.70	-
1	(SET) REAR BUMPER EXPENDER RIVET	NECESSARY	80.00	80.00
1	(SET) REAR BUMPER EXPENDER NUT	NOT NECESSARY	100.00	-
1	(SET) REAR BUMPER SENSOR O-RING	NOT NECESSARY	60.00	-
1	TAILLAMP (LH)	CRACKED / SCRATCHED	1,350.00	1,345.00
1	TAILLAMP SEAL (LH)	NOT NECESSARY	180.00	-
1	REAR FENDER (LH)(NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-723.68	-254.50
			6,513.12	2,290.50
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	60.00
1	SET TAILLAMP CLIPS (SN)	NOT NECESSARY	60.00	-
			220.00	60.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER (LH).		1,200.00	500.00
	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT.		80.00	20.00
	REMOVE & REFIT REVERSE SENSOR & CHECK.		100.00	50.00
	RESET ECU PROGRAMMING.		400.00	80.00
	APPLY UNDERCOATING FOR RUST ROOFING.	NOT NECESSARY	100.00	-

Report Ref No. CS/AGI22002300/Uvy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,600.00	550.00
			3,480.00	1,200.00
GRAND TOTAL			10,213.12	3,550.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/AGI22002300/Uvy3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.