

ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396 Email: absolute.app.svcs@gmail.com

Vehicle No: SND223L						Report No: AAS/2021/257				
Appraisement Schedule										
			~ 14.4					D	. 15.	
	S/N Parts Description		Qty Condition			Repairer's Est Revised Est \$ 26,112.86 22195 \$ 26,112.86				
1	Rear bumper	1	Dented		00546			22195 \$.	26,112.86	
2	Rear bumper lamp LH/RH	2	Refit	\$	385.16	\$	770.32	ф	-	
3	Rear bumper lower grille LH/RH	2 xn i		\$	2,170.13	\$	4,340.26	\$	4,340.26 x	
4	Rear bumper diffuser xnn	1	Cracked/Broken			\$	28,000.77		28,000.77 x	
5	Rear bumper emblem	1	Necessary			\$	549.08	\$	549.08	
6	Rear bumper crossmember	1	Refit			\$	8,900.00			
7	Rear bumper centre trellis	1	Dented			\$	280.02	\$	280.02	
8	Rear parking sensor	2	Refit	\$	464.80	\$	929.60		-	
9	Rear parking sensor ring	4	Necessary	\$	25.10	\$	100.40	\$	100.40	
10	Reverse camera	1	Refit			\$	3,778.31		-	
11	Reverse camera bracket xnn	1	Necessary			\$	56.36	\$	56.36 x	
			23124.50			_		_		
			10%	List	t total:	\$	73,817.98		59,439.75	
			20812.05							
S/N Labour Description						Repairer's Est Revised Est				
1	To remove & transfer rear parking	ig senso	ors & reverse camera.			\$	150.00	\$	60 100.00	
	-	_								
2	To check lightings & wirings. xnr	1				\$	50.00	\$	30.00 x	
7. The way and damaged marks Deform working a so align all affected area						¢	600.00	ď.	\$ 250 375 . 00	
3 To renew rear damaged parts. Reform, repair & re-align all affected area.						\$	600.00	\$ 230 373.00		
4 To respray front affected parts.						\$	500.00	\$2	250 400.00	
	rear									
				Labo	ur Total:	\$	1,300.00	- \$	905.00	
									560	
				Gran	ıd Total:	\$	75,117.98	• \$	60,344.75	
The	final adjusted lump sum amount i	s \$	48,300.00			·	,	-	ŕ	
The find adjusted famp sam amount is \$\psi_10,000.00								20812.05		
Under normal circumstances, the repair should be completed							•	560.00		
within a reasonable period of 4 working days.						21372.05				
						20%				
60 Photographs were taken at the time of inspection.								17097.64		

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

L/S-\$17100/3 DAYS