| ASS. REC. BY: . REF: US/EGIZZ                | 2002310/Rty3 364K   |
|--|---|
| ASSI   | GNMENT  |
| From: Date:                                  | Veh No: SHF 333M Yr Regn: 2019 / Oct                                |
| Estimated Cost:                              | Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /    |
| OD ITP/WS/TP RES/OD RES/EVA/INV/MV           | Truck / Trailer or  |
| To Inspect Vehicle No: SHF 3330              | Make: TOYOTA PRIMS SOR H. B.A c.c 1798                              |
| at Workshop m/s STRIPUS (SMRT)               | Colour MARGON A/C: Insured / Std / NI / NA                          |
| of bo, modernes lad PLEY                     | Sp.Reading 142947 T/Radio: Insured / Std / NI / NA                  |
| Insured: EG [.                               | Eng/No:   |
| Policy No.                                   | C/No: 3TDKB 3FU 303089401   |
| Claims No.                                   | Gen. Cond: Good / Fall / Poor / Burnt                               |
| Surn Insured: Excess:                        | Steering: Inforder/ Jammed / Leaked / Burnt or                      |
| (Client's Record)                            | Brake: in order / Jammed / Leaked / Burnt or                        |
| Make of Veh:                                 | Modi: MP/S/Rim / STD A/Rim or                                       |
|  | Tyre Size: F: 95/65R45  |
| (Policy Condition)                           | R:  |
| Remark: The veh had commenced its N/S O/S    | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /     |
| repair at the time of inspection.            | TOYO / YOKO or SA(LW  |
| Bal. or Market Value:                        | Front Rear  |
| IDAC Accident Rport: Consistent? : Yes or No | R/Bal. 6 mm R/Bal. 6 mm   |
| GIA / PR Seen: Consistent?: Yes or No        | L/Bal. 6 mm   |
| Est. Repairs: days Res.: Yes or No           | D.O.A. 10 03 22 D.O.I. 11 03 22                                     |
| Lum Sum: % 3 Val.: Yes or No                 | Survey held at STRIDES  |
| OA LATIL DED LOAUDE                          | Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or          |
| CA / REV / REP. / 24 HRS  Vehicle: IN / OU   | T OS REAL   |
| Dale: Person Contacted:                      | The U/C / Chassis frame / Body Structure affected due to collision. |
| Date / Time Action / Instruction             |   |
|  |   |
| advicing our principal                       | a cost of ropair of   |
| advising our principal                       |   |
| P/P \$2,101.18 /- with                       | 04 days of repair,  |
| red: 5,571.57;72%                            |   |
|  |   |
|  |   |
| Osto/Time File Page to 2                     | 4   |
| Date/Tline, File Pass to? : Preli. Report    | Days Of Repair:   |
| 1) : Final Report                            | Resurvey No. of Trip: Survey Fee:                                   |
| Date/Time, File Return to?                   | Transportation:   |
| 2) Add F                                     | ee:: Site Insp (\$)s+Rssi   |
|  | : Interview (\$ ) Photos  |
| Reput Formet:                                | : Tech. Invs (\$ ) Others   |
| Lump Sum / I.B.J: (†)                        | : Weel:end (\$  |
|  | TOTAL   |



### Case Details

Case Reference Number : TAX/03/22/2023

Type of Repair : Accident Repair

Vehicle Registration Number : SHF333M

Company Type: Strides Taxi Pte Ltd

Estimation ID: EST-17703-ID

Assigned By: Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd

Accident Date and Time: 10/03/2022 03:40 AM

Vehicle Age(In Months): -

# Documents / Photographs

View Documents / Photographs

Total Documents: 0

# **Estimation Details**

#### Spare Part's Cost Detail

|             |                 |         |                    | SMRT Recom                             | menda | ation                            |                   |        |                    |                    |                      | Surve                          | yor Approval   |         |
|-------------|-----------------|---------|--------------------|--|-------|----------------------------------|-------------------|--------|--------------------|--------------------|----------------------|--------------------------------|----------------|---------|
| BOM<br>Type | Costing<br>Type | Portion | Material<br>Number | Part Name                              | Qty   | List<br>Price<br>Per<br>Unit(\$) | List<br>Price(\$) | Dis(%) | Final<br>Price(\$) | Repair/<br>Replace | Surveyor<br>Quantity | Surveyor<br>Final<br>Price(\$) | Repair/Replace | Remarks |
| Standard    | Main            |         |                    | COVER, RR<br>BUMPER ASSY               | 1     | 485.60                           | 485.60            | 25.00  | 364.20             | Replace            | 1                    | 0                              | Repair ∨       | R       |
| Standard    | Main            |         |                    | PAD, RR<br>BUMPER, RH &<br>LH , 3      | 2     | 11.00                            | 22.00             | 25.00  | 16.50              | Replace            | 0                    | 0                              | Not Giv∈ ∨     | X17     |
| Standard    | Main            |         |                    | PAD, RR<br>BUMPER, RH &<br>LH, 2       | 2     | 4.00                             | 8.00              | 25.00  | 6.00               | Replace            | 0                    | 0                              | Not Giv€ ✔     | X17     |
| Standard    | Main            |         |                    | PAD, RR<br>BUMPER, RH &<br>LH , 1      | 2     | 4.00                             | 8.00              | 25.00  | 6.00               | Replace            | 0                    | 0                              | Not Giv∈ ✓     | Xnn     |
| Standard    | Main            |         |                    | RETAINER, RR<br>BUMPER, RH             | 1     | 132.60                           | 132.60            | 25.00  | 99.45              | Replace            | 0                    | 0                              | Not Giv€ ✔     | Kun     |
| Standard    | Main            |         |                    | PANEL SUB-<br>ASSY, REAR<br>DOOR , RH  | 1     | 1,294.90                         | 1,294.90          | 25.00  | 971.18             | Replace            | 1                    | 971.18                         | Replace 💙      | 41      |
| Standard    | Main            |         |                    | CHECK ASSY,<br>REAR DOOR               | 1     | 183.80                           | 137.85            | 25.00  | 137.85             | Replace            | 0                    | 0                              | Not Giv∈ ✓     | X11     |
| Standard    | Main            |         |                    | WEATHERSTRIP,<br>REAR DOOR RH          | 1     | 180.10                           | 180.10            | 25.00  | 135.08             | Replace            | 0                    | 0                              | Not Giv€ ✓     | XM      |
| Standard    | Main            |         |                    | DOOR OUTER<br>HANDLE REAR ,<br>RH      | 1     | 97.40                            | 97.40             | 25.00  | 73.05              | Replace            | 1                    | 0                              | Repair 🗸       | R       |
| Standard    | Main            |         |                    | DOOR LOCK<br>REAR , RH                 | 1     | 561.90                           | 561.90            | 10.00  | 505.71             | Replace            | 0                    | 0                              | Not Giv€ ✓     | XM      |
| tandard     | Main            |         |                    | HINGE ASSY,<br>REAR DOOR ,<br>LOWER RH | 1     | 87.10                            | 65.32             | 25.00  | 65.32              | Replace            | 0                    | 0                              | Not Giv€ ✓     | Xv.     |
| Standard    | Main            |         |                    | HINGE ASSY,<br>REAR DOOR ,<br>UPPER RH | 1     | 98.90                            | 74.18             | 25.00  | 74.18              | Replace            | 0                    | 0                              | Not Giv€ ✔     | XV      |

Total Spare Part Cost 4,713.08

Surveyor Total 971.18

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 4,713.08

Final Sur Total 971.18

| 1           |                 |         |                    | SMRT Recom  | menda | ation                            |                   |          |                    |                    |                      | Surve                          | yor Approval   |         |
|-------------|-----------------|---------|--------------------|---|-------|----------------------------------|-------------------|----------|--------------------|--------------------|----------------------|--------------------------------|----------------|---------|
| вом<br>Туре | Costing<br>Type | Portion | Material<br>Number | Part Name   | Qty   | List<br>Price<br>Per<br>Unit(\$) | List<br>Price(\$) | Dis(%)   | Final<br>Price(\$) | Repair/<br>Replace | Surveyor<br>Quantity | Surveyor<br>Final<br>Price(\$) | Repair/Replace | Remarks |
| Standard    | Main            |         |                    | DOOR REAR<br>MOTOR ASSY,<br>POWER<br>WINDOW<br>REGULATOR,<br>RH | 1     | 926.00                           | 926.00            | 10.00    | 833.40             | Replace            | 0                    | 0                              | Not Giv€ ❤     | X11     |
| Standard    | Main            |         |                    | DOOR REAR<br>WINDOW<br>REGULATOR<br>SUB-ASSY, RH                | 1     | 206.70                           | 206.70            | 25.00    | 155.02             | Replace            | 0                    | 0                              | Not Giv€ ➤     | X11     |
| Standard    | Main            |         |                    | MEMBER SUB-<br>ASSY, RAIL<br>ROOT SIDE<br>REAR RH               | 1     | 288.50                           | 288.50            | 25.00    | 216.38             | Replace            | 0                    | 0                              | Not Giv€ ✔     | Ynn     |
| Standard    | Main            |         |                    | PANEL SUB-<br>ASSY, FENDER<br>REAR RH                           | 1     | 871.50                           | 871.50            | 25.00    | 653.63             | Replace            | 1                    | 0                              | Repair V       | R       |
| Standard    | Main            |         |                    | PATCH, SIDE<br>PANEL REAR<br>END , RH & LH                      | 1     | 33.70                            | 33.70             | 25.00    | 25.28              | Replace            | 0                    | 0                              | Not Giv€ ✓     | Kan     |
| Standard    | Main            |         |                    | LINER, REAR<br>FENDER , RH                                      | 1     | 139.80                           | 139.80            | 25.00    | 104.85             | Replace            | 0                    | 0                              | Not Giv€ ✔     | Kan     |
| Standard    | Main            |         |                    | DUCT ASSY,<br>QUARTER VENT<br>, RH & LH                         | 1     | 67.00                            | 67.00             | 25.00    | 50.25              | Replace            | 0                    | 0                              | Not Giv∈ ❤     | Xng     |
| Standard    | Main            |         |                    | WEATHERSTRIP,<br>REAR DOOR<br>OPENING TRIM,<br>RH               | 1     | 293.00                           | 293.00            | 25.00    | 219.75             | Replace            | 0                    | 0                              | Not Giv€ ♥     | X11     |
|             |                 |         |                    |   |       | To                               | otal Spare P      | art Cost | 4,713.08           |                    | Sui                  | veyor Total                    | 971.18         |         |
|             |                 |         |                    |   |       | Lum                              | p Sum Disc        | ount (%) | 0.00               |                    | Lump S               | Sum Dis (%)                    | 0              |         |
|             |                 |         |                    |   |       | Fi                               | inal Spare P      | art Cost | 4,713.08           |                    | Fin                  | al Sur Total                   | 971.18         |         |

### Labour's Cost Detail

| S.No.  | Costing Type | Job Scope            | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|----------------------|----------------------------|----------------------------|---------|
| , 1    | Main         | TO REPAIR RH PORTION | 845.00                     | 400                        |         |
| Total: |              |                      | 845.00                     | 400.00                     |         |

### Spray Cost Detail

nm

| S.No. | Costing Type | Job Scope                 | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|-------|--------------|---------------------------|----------------------------|----------------------------|---------|
| 1     | Main         | TO RESPRAY DOOR HANDLE    | 180.00                     | 30                         |         |
| 2     | Main         | TO RESPRAY RH REAR DOOR   | 378.00                     | 200                        |         |
| 3     | Main         | TO RESPRAY REAR FENDER RH | 378.00                     | 200                        |         |
| 4     | Main         | TO RESPRAY REAR BUMPER    | 378.00                     | 200                        |         |
| otal: |              |                           | 1.314.00                   | 630.00                     |         |

1,314.00

630.00

# Other Cost Detail

| S.No.  | Costing Type | Job Scope                                  | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|--|----------------------------|----------------------------|---------|
| 1      | Main         | TO WASH AND VACUUM                         | 60.00                      | · XM                       |         |
| 2      | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA    | 100.00                     | 40                         |         |
| 3      | Main         | TO REPLACE SUNDRY PARTS                    | 100.00                     | o Xnn                      |         |
| 4      | Main         | TO TRANSFER DOOR MECHANISM                 | 120.00                     | 60                         |         |
| 5      | Main         | TO TEST AND REFIX REVERSE<br>SENSOR SYSTEM | 120.00                     | ο Xνν                      |         |
| Total: |              |  | 500.00                     | 100.00                     | A       |

# Summary

|                        | Estimator Assesment(\$)  | Surveyor Assesment(\$)                              |
|------------------------|--|---|
| otal Spare Part Detail | 4,713.08   | 971.18  |
| otal Labour Cost       | 845.00   | 400.00  |
| tal Spray Painting     | 1,314.00   | 630.00  |
| her                    | 500.00   | 100.00  |
| verall Total           | 7,372.08   | 2,101.18  |
| mp Sum Repair Option   |  |   |
| mp Sum Total           | 0.00   | 2,101.18  |
| rveyor Approved Amount |  | 2,101.18  |
| of Repair Days*        | 6  | 4   |
|                        | The state of the s |   |
| marks                  |  | PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO . |
| rveyor Name            |  | Rasul   |
| nature                 | the street of the contract of the second   |   |

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Survey DateSupplementary item(s) must be resurveyed and is subject to final approval from Insurance Company2022

Acknowledged by Repairer

Signature:

SS27223A0003 / Strides Automotive Services Pte Ltd 



# SINGAPORE ACCIDENT STATEMENT

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

10/03/2022 14:02 (SGT) Date of Submission 10/03/2022 11:40 (SGT) **Date of Accident** 37 Keppel Rd, Singapore 089064 **Exact Location of Accident** BLK 37 KEPPEL ROAD CAR PARK Additional Location Information Singapore Country/State of Loss

### DETAILS OF OWN VEHICLE

1800

SHF333M Vehicle Registration Number

INSURED/POLICYHOLDER

Yes Is company? Strides Taxi Pte Ltd Name Of Registered Owner 1XXXXX369K Company Reg No AUTO-SVCS-TARC@SMRT.COM.SG **Email Address** (Phone) +65-68662671 Mobile Phone No (Office) +65-68662672 Alternative Phone No

VEHICLE PARTICULARS

Toyota Manufacturer **Prius** Model Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Taxi Vehicle Category Auto Transmission

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd Type of Coverage ThirdParty Fleet Policy D-21097466MFSH **Policy Number** Cover Note Number

DRIVER

CC

Name of Driver HO SWEE HUAT MERVIN NRIC No SXXXX065F




Date Of Birth 15/06/1960 Occupation Outdoor Date Of Driving Pass 14/07/1978 Driving experience 43 YEARS AND 8 MONTHS Gender Male Mobile Number (Phone) +65-68662672 Alt. Phone Number **Email Address** AUTO-SVCS-TARC@SMRT.COM.SG Address 11 Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Side Swipe Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 5 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name **MEEKHI** Gender Female PASSENGER 2 Name UNKNOWN Gender Female PASSENGER 3 Name UNKNOWN Gender Male PASSENGER 4 Name UNKNOWN Gender Male **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG THE CAR PARK OF BLK 37 KEPPEL ROAD WITH 4 PASSENGERS( 2 MALE/ 2 FEMALE CHINESE) ON BOARD. WHILST I WAS TRAVELLING STRAIGHT, A VEHICLE GBK9029C DROVE THROUGH THE PARKING LOT AND TURN OUT ABRUPTLY INTO MY PATH AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

ATTACHMENT(S)



Are accident photos available for attachment?
Was there any video captured by Car Camera?
Reasons for not uploading a video of the accident
Was there any audio recorded?

Yes Yes FILE TOO BIG No

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBK9029C Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

## **WITNESS DETAILS**

WITNESS 1

Name MEEKHI
Phone Email -

| BK37. |   |  |
|-------|---|--|
| 1     | 8 |  |

#### Declaration

nc

in.

I'We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) "Date & Time

Witnessed by Reporting Centre Personner

## SKETCH PLAN

# IMPORTANT NOTICE

- 1. Flease report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

#### (collectively the 'Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (# driver/is not the policyholder) / Date & Tirre

Witnessed by Reporting Centre Personnel

10.3.2022

Sketch Plan

ist R

3 \

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type:                | Company   |
|-------------------------------|---|
| Owner ID:                     | 369K  |
| Vehicle No.:                  | SHE333M   |
| Vehicle to be Exported:       | No.   |
| Intended Deregistration Date: | 13 Mar 2022   |
| Vehicle Make:                 | TOYOTA  |
| Vehicle Model:                | PRIUS 5DR HATCHBACK (AUTO)  |
| Primary Colour:               | Maroon  |
| Manufacturing Year:           | 2019  |
| Engine No.:                   | 2ZR2F43489  |
| Chassis No.:                  | JTDKB3FU303089401   |
| Maximum Power Output:         | 90.0 kW (120 bhp)   |
| Open Market Value:            | \$26,807.00   |
| Original Registration Date:   | 26 Dec 2019   |
| First Registration Date:      | 26 Dec 2019   |
| Transfer Count:               | 0   |
| Actual ARF Paid:              | \$14,530.00   |
| PARF Eligibility:             | Yes Land Application of the Control |
| PARF Eligibility Expiry Date: | 25 Dec 2027   |
| PARF Rebate Amount:           | \$10,897.00   |
| COE Expiry Date:              | 25 Dec 2027   |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp)  |
| COE Period(Years):            | 8   |
| PQP Paid:                     | \$25,581.00   |
| COE Rebate Amount:            | \$18,489,00   |
| Total Rebate Amount:          | \$29,386.00   |

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Mar 2022