

J.E.W MOTORS PTE LTD

Address: 60 Jalan Lam Huat, #03-72
CARROS CENTER, Singapore 737869

Repair Estimate

Vehicle number: GBK708K
Model and make: Toyota Dyna

No.	Spare parts	Qty	Amount
1	Tailgate	1	\$ 1,137.10 / DT
2	Tailgate "Dyna" sticker	1	\$ 61.00 / NIC
3	Tailgate LH side hinges	1	\$ 123.10 X Svc
4	Tailgate LH centre hinge	1	\$ 123.10 X Svc
5	Tailgate RH centre hinge	1	\$ 123.10 / DT
6	Tailgate RH side hinge	1	\$ 123.10 / DT
7	Tailgate RH flip lock	1	\$ 237.50 / DT
8	Tailgate LH flip lock	1	\$ 237.50 X Svc
9	Tailgate lower panel	1	\$ 473.00 / DT
10	Tailgate LH rubber stopper	1	\$ 28.30 X HKS Svc
11	Tailgate LH rubber stopper bracket	1	\$ 129.30 + BKF Svc
12	Tailgate RH rubber stopper	1	\$ 28.30 / mis
13	Tailgate RH rubber stopper bracket	1	\$ 129.30 / DT
14	RH taillamp	1	\$ 164.10 - Crg
15	RH taillamp panel	1	\$ 113.10 X Svc
16	LH taillamp	1	\$ 164.10 X Svc
17	LH taillamp panel	1	\$ 113.10 X Svc
18	RH side gate	1	\$ 1,409.80 / DT
19	LH side gate	1	\$ 1,409.80 X Svc
20	Exhaust pipe	1	\$ 494.40 X Svc Xv
21	Exhaust pipe gasket	1	\$ 33.00 X Svc
22	Exhaust pipe rubber hanger bracket	1	\$ 38.40 X Svc
23	Exhaust pipe rubber hanger	1	\$ 87.20 X Svc / mis
24	Exhaust pipe rubber hanger bracket clamp	1	\$ 21.30 X Svc
25	Spare tyre carriage	1	\$ 325.70 X Svc
26	Rear number plate lamp	2	\$ 137.40 X Svc
27	Rear number plate bracket	1	\$ 148.30 X Svc
			\$ 7,613.40
less parts 25%			\$ 1,903.35
Total			\$ 5,710.05

No.	Spare parts	Qty	Special Nett
1	Tailgate advertisement sticker	1	\$ 550.00 X 100 nec
2	Tailgate "70km/h" sticker	1	\$ 28.00 / nec

3	Tailgate "13pax" sticker	1	\$	28.00 / nec
4	Tailgate inner aluminium panel	1	\$	750.00 750.00 / MT PTC 300
5	Tailgate inner aluminium panel rivets	1set	\$	70 180.00 / MC PTC
6	Tailgate lower panel sealant	1	\$	80.00 XRCN
7	Rear number plate	1	\$	70.00 40 BT
8	Rear step bracket	1	\$	460 780.00 / BT PTC
9	Rear reverse sensor with bracket	1	\$	400.00 200 cut
10	RH side gate inner aluminium panel	1	\$	850.00 Xsrc
11	RH side gate inner aluminium panel rivets	1set	\$	230.00 Xsrc
12	LH side gate inner aluminium panel	1	\$	850.00 Xsrc
13	LH side gate inner aluminium panel rivets	1set	\$	230.00 Xsrc
14	Rear platform aluminium panel	1	\$	800 1,250.00 / MT PTC 800
15	Rear platform aluminium panel rivets	1set	\$	280.00 Xsrc
16	Spare tyre (big)	1	\$	450.00 Xsrc
17	Spare tyre (small)	1	\$	320.00 Xsrc
18	Canopy rear enforcement beam RH	1	\$	850.00 Xsrc
19	Canopy rear enforcement beam LH	1	\$	850.00 Xsrc

LABOUR

1	Labour charges to provide workmanship cut / weld and replacing of parts	\$	1,800.00 500
2	Spray paint on affected and consistent areas	\$	1,500.00 500
3	Check wiring and lighting system	\$	120.00 30
4	Apply rust chemical on affected areas	\$	150.00 30
5	Remove and replace rear reverse sensors	\$	100.00 30
6	Replace and alignment tailgate, side gates inner aluminium panels and rivets	\$	650.00 400 100
7	Remove and replace exhaust pipe and gasket	\$	220.00 40
8	Remove, reinstall and replace canopy assy for repair. To replace affected items	\$	800.00 100

Total: \$ 20,076.05

Thuan@Lkhauto.com

82235769

L/S 4days w/p

14/3/22 1600

F: 5/00

RP: 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: