



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300461

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/01/2023
Reference CC6/CTI22002320/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 4854K
Insured Veh. GBB 3605B
Claim No. SNM22D201772/C02
Policy No. DMCVSNW000003392211
Accident Date 13/03/2022
Inspection Date 15/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22002320/Dpa3q2 Date: 20/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 3605B	Veh. Inspected	SHD 4854K	
Policy No.	DMCVSNW000003392211	Coverage (\$)	0.00	
Claim No.	SNM22D201772/C02	Excess (\$)	0.00	
Assign From		Assign Date	15/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVKU164650	Colour	BLUE	
Odometer	277127 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/03/2022	Inspection Date	15/03/2022	
Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4854K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT DOOR (LH)	BUCKLED	1,797.20	1,797.20
1	FRT DOOR RUBBER	NECESSARY	250.00	250.00
1	FRONT DOOR REGULATOR (LH)	CRACKED / BROKEN	750.40	750.40
1	FRT DOOR POWER MOTOR ,LH	NOT NECESSARY	689.20	-
1	FRONT DOOR OUTER HANDLE (LH)	NOT NECESSARY	234.80	-
1	FRONT DOOR TRIM BOARD (LH)	MTG BROKEN	796.80	796.80
1	FRONT DOOR PROTECTOR (LH)	NECESSARY	186.20	186.20
1	REAR DOOR (LH)	BUCKLED	1,789.90	1,789.90
1	REAR DOOR RUBBER (LH)	NECESSARY	280.00	280.00
1	REAR DOOR OUTER HANDLE (LH)	NOT NECESSARY	124.80	-
1	REAR DOOR GEAR /REGULATOR (LH)	MTG CRACKED	367.84	367.84
1	REAR DOOR POWER MOTOR (LH)	NOT NECESSARY	256.80	-
1	REAR DOOR LOCK ASSY	NOT NECESSARY	306.40	-
1	REAR DOOR HINGE UPPER (LH)	NOT NECESSARY	173.88	-
1	REAR DOOR HINGE LOWER (LH)	BENT	170.50	170.50
1	REAR DOOR CHECKER (LH)	NOT NECESSARY	85.92	-
1	REAR DOOR TRIM BOARD (LH)	MTG CRACKED	613.60	613.60
1	REAR DOOR PROTECTOR (LH)	NECESSARY	166.20	166.20
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	3,764.90	3,764.90
1	ROCKER PANEL OUTER GARNISH	NOT NECESSARY	715.60	-
1	ROCKER PANEL OUTER GARNISH CLIP	NOT NECESSARY	65.00	-
1	REAR BUMPER	MTG BROKEN	459.40	459.40
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
1	REAR BUMPER SIDE RETAINER (LH)	NOT NECESSARY	85.80	-
1	REAR BUMPER COVER CLIPS	NOT NECESSARY	22.00	-
1	REAR FENDER (LH)	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR FENDER SHIELD REAR PIECE (LH)	NOT NECESSARY	173.60	-
1	REAR FENDER SHIELD FRT PIECE (LH)	NOT NECESSARY	165.50	-
1	REAR TYRE RIM (LH)	NOT NECESSARY	1,124.20	-

Report Ref No. CC6/CTI22002320/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WHEEL HUP-CAP (LH)	CUT	346.40	346.40
1	REAR WHEELBEARING & HUB ASSY	NOT NECESSARY	554.00	-
1	REAR TRAILING ARM (LH)	NOT NECESSARY	265.40	-
1	REAR ASSIST (LH)	NOT NECESSARY	227.90	-
1	REAR SHOCK ABSORBER (LH)	NOT NECESSARY	230.50	-
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	133.10	-
1	REAR ABSORBER STOPPER (LH)	NOT NECESSARY	137.60	-
1	REAR ABSORBER COVER (LH)	NOT NECESSARY	175.60	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,468.70	-
1	STABILIZER BAR	NOT NECESSARY	387.30	-
1	STABILIZER LINK (LH)	NOT NECESSARY	147.30	-
1	REAR UPPER ARM (LH)	NOT NECESSARY	239.50	-
1	REAR LOWER ARM (LH)	NOT NECESSARY	393.10	-
1	REAR KNUCKLE ARM (LH)	NOT NECESSARY	538.10	-
	LESS 20% DISCOUNT		-4,553.47	-2,347.87
			18,213.87	9,391.47
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMFORT LOGO (LH) (SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR TEL NO.STICKER (LH) (SN)	NOT FITTED	10.00	-
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	ROCKER PANEL OUTER GARNISH ADVERTISEMENT (SN)	NOT NECESSARY	100.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER ADVERTISEMENT (LH) (SN)	NECESSARY	120.00	120.00
1	REAR TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			901.00	525.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER (LH).		1,800.00	1,000.00

Report Ref No. CC6/CTI22002320/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		1,600.00	900.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR .		150.00	80.00
	REMOVE /REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).	NOT NECESSARY	400.00	-
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE/REFIX EXHAUT PIPE .	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM FRONT .		80.00	60.00
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	TRANSFER OF DOOR MECHANISM REAR .		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.}		550.00	150.00
	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR .}		550.00	-
			6,690.00	2,350.00
GRAND TOTAL			25,804.87	12,266.47

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,000.00
---	--	--	------------------

Report Ref No. CC6/CTI22002320/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4854K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4854K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4854K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

