

OC6/CTI22002320/Dga³

ASSIGNMENT

COE July 2027

Estimated Cost:
) / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s

Insured:

Policy No.

Claims No.

Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value:

JAC Accident Rpt:

Consistent? : Yes or No

IA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Sum Sum:

10 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Vehicle No: **STD 4854K** Regd: **July 2019**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

C.C. **1580**

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp Reading:

277127

T/Radio: Insured / Std / NI / NA

Eng/No:

G4LEK4297723

C/No:

KMHCB51CVK4164650

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

195/65 R 15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal:

S

mm

R/Bal:

S

mm

L/Bal:

S

mm

L/Bal:

S

mm

D.O.A:

13/03/2022

D.O.I:

15/03/2022

Survey held at

Bifrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China Teiping GBS 3605B

02/09/22

judged L/S 11,000/- with 8 days of work

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp: 1%

☐

Interview: 1%

☐

Final Report: 1%

☐

Other: 1%

1-1-1-1-1

1-1-1-1-1

1-1-1-1-1