

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 61136**  
Date Estimated : **09/03/2022**  
Prepared By : **Inthiran A/L Thurasamy**

**- ESTIMATE REPAIR FOR -**  
**Ong Wee Liam (Wang Weilian)**  
**312B Anchorvale Lane**  
**#12-70**

**Singapore 542312**

**- ACCOUNT - 135**  
**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLG1127H</b>	<b>WBA5F32070FJ63743</b>	<b>15/10/2020</b>	<b>320i Sedan</b>	<b>26425</b>

DESCRIPTION	ORIGINAL PRICE	NETT
To replace rear bumper and attachments including remove attachments to facilitate repair.	850.00	850.00
To respray rear bumper.	986.00	986.00
To remove old PDC assembly and reconnect to new bumper including conduct check for proper function.	168.00	168.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	168.00
Sundries.	80.00	80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
REAR BUMPER CARRIER	493.80	1.00	493.80
ADAPTER	48.35	1.00	48.35
REAR BUMPER PANEL PRIMED (BASIS PDC	1,262.20	1.00	1,262.20
REAR DIFFUSER	71.30	1.00	71.30

### # SUPPLEMENTARY ITEMS

Total Labour :	2,252.00
Total Parts :	1,875.65
Total Labour & Parts :	4,127.65
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,127.65
GST @7%:	288.94
Grand Total :	4,416.59