

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

<b>TO</b>	: AXA	<b>DATE</b>	: 14/03/2022
<b>ATTENTION</b>	: MOTOR CLAIMS DEPT	<b>JOB TYPE</b>	: T/P CLAIM
<b>ESTIMATE REPORT</b>	:	<i>WMWXUS2000270713</i>	
<b>VEHICLE DETAILS</b>			
<b>VEHICLE NO</b>	: SMY1196B	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p>	
<b>MODEL</b>	: MINI ONE		
<b>CHASSIS NO</b>			
<b>ACCIDENT DETAILS</b>	<b>DATE</b> : 11-Mar-22 <b>TIME</b> : 17:10HRS		
<b>THIRD PARTY REQUESTOR / CONTACT</b>	: JACK LI		

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	TAILGATE <i>Repis</i>	1	\$ 2,553.40	\$ 2,553.40	x
2	TAILGATE EMBLEM ONE <i>new</i>	1	\$ 80.00	\$ 80.00	-
3	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 280.00	\$ 280.00	x
4	REAR BUMPER <i>Delnd</i>	1	\$ 1,855.30	\$ 1,855.30	999.
5	RERAR BUMPER LOWER <i>Delnd</i>	1	\$ 680.50	\$ 680.50	321
6	REAR BUMPER SIDE RETAINER <i># new</i>	2	\$ 133.50	\$ 267.00	x
7	REAR BUMPER CENTRE LIGHT <i>new</i>	1	\$ 397.30	\$ 397.30	x.
8	REAR BUMPER TOWING COVER <i>Delnd</i>	1	\$ 60.00	\$ 60.00	-
9	REAR BUMPER CENTRE FRAME <i>new</i>	1	\$ 266.50	\$ 266.50	-
10	REAR BUMPER REINFORCEMENT BAR <i>Dented</i>	1	\$ 860.70	\$ 860.70	683
11	REAR BUMPER REVERSE SENSOR <i>new</i>	2	\$ 220.50	\$ 441.00	-
12	REAR BUMPER REVERSE SENSOR RUBBER <i>new</i>	4	\$ 30.00	\$ 120.00	60.
13	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	\$ 35.00	\$ 140.00	60.
14	WHEEL ARCH PROTECTOR RH <i>new</i>	1	\$ 211.90	\$ 211.90	-
15	TAILLAMP LH <i>new</i>	1	\$ 580.50	\$ 580.50	-
16	TAILLAMP COVER LH <i>new</i>	1	\$ 188.50	\$ 188.50	-
17	REAR EXHAUST PIPE <i>new</i>	1	\$ 3,200.00	\$ 3,200.00	x
18	REAR EXHAUST PIPE HEAD <i>new</i>	1	\$ 211.50	\$ 211.50	-

19	REAR EXHAUST SHIELD HEAT <i>Nec</i>	1	\$ 280.30	\$ 280.30
			TOTAL PRICE	\$ 12,674.40
			LESS 5%	\$ 633.72
			<b>SUB TOTAL PRICE</b>	<b>\$ 12,040.68</b>

*406250*  
*395475*

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS(SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00
2	REAR BUMPER CENTRE FRAME CLIPS(SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00
3	REAR FENDER PROTECTOR CLIPS(SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00
<b>TOTAL</b>				<b>\$ 60.00</b>

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING**

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ <del>1,200.00</del>	<i>300</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ <del>1,000.00</del>	<i>500</i>	
3	WIRING CHECK	\$ <del>80.00</del>	<i>30</i>	
4	TUFF COAT	\$ 250.00	<i>X</i>	
5	TO REMOVE AND RFEFIX REAR REVERSE SENSOR	\$ <del>100.00</del>	<i>60</i>	
6	TO REMOVE AND RFEFIX REAR EXHAUST PIPE	\$ 300.00	<i>X</i>	
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ <del>320.00</del>	<i>X 120.</i>	

**TOTAL**

**\$3,250.00**

**ESTIMATE REPORT**

TOTAL PARTS COST \$ 12,100.68  
 TOTAL LABOUR COST \$ 3,250.00  
 TOTAL REPAIR COST \$ 15,350.68

**APPROVED DETAILS**

**SURVEYOR**

*LKK Auto Consultants hence notify the Repairer of the following:*  
 • To survey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Surveys only item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

*Admin*

*1/5 12/03/22*

*03 Days*

*Total: 5024/25*

*h/s: 3AK*

*AK*

*1010*

*60*