

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002340/AQY3N2**Date:** 28/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00110282100

Claimant Vehicle No : SMH8596Z **Insured Vehicle No :** YQ6828D

Date of Loss: 10/03/2022 Nature of Claim: TP Claim No: SNM22D201708/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH8596Z**

Make & Model: HONDA VEZEL HYBRID, 1.5 x (A) Engine No: LEB6744227

Reg. Date: 12/02/2019 (Man. Year: 2018) Chassis No: RU31324217

Colour: Blue Odometer: 249549 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,712.10	2,870.00	2,842.10	49.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	880.00	570.00	39.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,162.10	3,750.00	3,412.10	47.64
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	7,162.10	3,000.00	4,162.10	58.11

INSPECTION

Date of Assignment: 14/03/2022

Date Inspected: 22/03/2022 Inspected At: JEC AUTO SERVICE PTE LTD (HQ)
1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2022)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 x (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8596Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	785.40 F	*785.40 FL
2	1		*FRONT BUMPER SIDE HOLDER LH	Not Necessary	28.40 F	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	321.00 F	*- FL
4	1		*HEADLAMP LH	Cracked	2,135.40 F	*2,135.40 FL
5	1		*HEADLAMP LOWER BRACKET LH	Cracked	45.40 F	*45.40 FL
6	1		*FRONT LH FENDER	Not Necessary	580.50 F	*- FL
7	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	151.80 F	*- FL
8	1		*FRONT LH FENDER WHEEL ARC GARNISH	Cracked	183.80 F	*183.80 FL
9	1		*BONNET	Repair	1,020.40 F	*- FL
10	1		*BONNET DECORATIVE STICKER	Necessary	380.00 FS	*300.00 FS
11	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
13	1		*FRONT LH FENDER WHEEL ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
					Sub Total (\$\$)	5,712.10 3,500.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 630.00
					Total Parts (\$\$)	5,712.10 2,870.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	400.00
2	SPRAY PAINTING	New	800.00	450.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (\$)			1,450.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >